Helpful Information

Before completing the template it is best to do an informal interview with the individual in charge of the facilities. This is especially helpful when completing the checklists i.e., ADA, Harmful Substances, etc. Please ensure that you are interviewing the correct person to complete the checklists. For example, you may need to talk to the Internet Service Provider to complete the IT checklist. It is recommended that you complete the assessment on-site. Enter percentages and levels of action onsite after the walkthrough and before leaving the facility. In order for the template to accurately calculate information please complete the "Base Information Sheet." Cells highlighted in yellow are required as the rest of the template will not calculated correctly without that information. In order for the template to function properly do not change information on the READ ONLY tabs (worksheets e.g., "Building Type Budget-READ ONLY") It is best to use the template in Microsoft Excel as mobile devices and other application platforms such 6 as Apple will not show the comments. However, a "Physical Assessment Comments" tab is located in the template. Make sure you hover over the upper right hand corner of cells to view comments. They determine the level of action. Pay attention whether a comment says "and" or "or." 8 Use "x" to indicate a system is present. 9 Use "0" to indicate that a system is not present. When entering data in the Percentage of System column (column P), the data must be entered as a percentage of the system. For example, if resilient tile covers 50% of the building and 35% of it needs to 10 be replaced, used 35 in the Percentage of System column. This is true even if the system is a number rather than percentage. For example there are 40 wood doors and 10 need to be replaced, then enter 25 in Percentage of System column (Column P). When you are using your expertise to override the built-in cost model document that decision in the "Notes" sections. Notes must be added so the state and districts know why you are overriding the 11 template. Example, a system has a key component that needs to be replaced but that replacement is not accurately described in the "Level of Action" comments. If you have a system not found in the template then add it at the bottom of the "Physical Condition" Assessment." If you know that costs have changed override the cost on the Physical Condition Assessment tab ONLY 13 and note it. Please note that some units of measure differ from the gross square footage of the building. The new units of measure are provided as comments in the category description. This is to address some of the concerns with using gross square footage for units that aren't really based on square footage. Example: the percentage of exterior doors that are wood is the number of wood exterior doors divided by the total number of exterior doors. If a school has 10 exterior doors and 7 are wood, then 70% of the doors are wood and that is the percentage that goes into the % of Building column. 15 Please create a different assessment Excel workbook for each building. The default for portables is to list them in the Renovations, Additions, & Prtbls tab. If a district requests a 16 full assessment of their portable classrooms, please create a separate assessment Excel workbook for each building. If an ADA deficiency is listed in the Physical Condition Assessment tab, then include that in the final 17 costs. However, please do not add costs to the final amounts simply to bring building into ADA compliance. Please remember that this tool is to provide the districts and state with budget level estimates on costs of repairs to buildings. If after reviewing the total costs, including the built in soft cost multiplier, your expert opinion is that the costs are too low, please increase the costs and note it in the "Notes" section.

Base Information Sheet

Item	Data	Notes / Explanation
District Name:	John Day SD 3	Pull-down menu of the 197 Districts
Site Name:	Humbolt Elementary School	Typically the name that is used for the facility / campus
Building Name:	Humbolt Elementary School	If only one building on site, refer to "main"
Building ID:	2008010	Please use the same ID that is assigned to this building in the annual Building Collection.
Building Type:	Elementary School	Pull-down menu - feeds FCI calculation
Physical Address of Building:	329 North Humbolt Street, Canyon City, OR 97820	Informational only - does not link
Original Year of Building Completion	195	6 When was the original building completed and ready for use
Original Construction Type	Wood Framed and Sided	What type of construction was used to complete original building
Describe Other Construction Type		If you choose other construction type please describe here
County:	Grant	Pull-down menu of the 36 counties - sets location factor for budgets
Gross Square Footage:	40,570	Calculated from exterior face of walls (excluding eaves, outbuilding, porches, canopies, and similar)
Site Acreage:		District records
Assessor Company:	BLRB Architects	Certified company
Assessor Name:	Richard Higgins	For follow up questions
Contact (Phone):	503 860 4272	_
Contact (E-Mail): Date of Assessment:	rhiggins@blrb.com	Might reference back for inflation calculation (future)

^{*}Building ID Format: Located in ODE "Buildings Collection" database

District Name:

Site Name:

Building ID:

John Day SD 3

Humbolt Elementary School Building Name: Humbolt Elementary School

REMINDER: FILL OUT ALL INFORMATION ON 'BASE INFORMATION SHEET' BEFORE ENTERING DATA ON THIS SHEET

An unused cell or system that should not receive direct user input

An automatically populated cell from user input elsewhere in the file - do not overwrite

					LEVEL OF ACTIO	N		1		
Level 1 Level 2 Level 3	Type (as ap	% of Building pplicable) or Number	None	Minor	Moderate	e Major	Replace as part of Renovatio n	% of System or Finish	Automated Budget Estimate	Notes
A SUBSTRUCTURE										
A10 Foundations A1010 Standard Fo	oundations	0%	None	Minor	Moderate	Major	Replace	0%	\$0	
A1020 Special Fou		0%	None	Minor	Moderate	Major	Replace	0%	\$0	
A1030 Slab on Gra		100%	None	Minor	Moderate	x Major	Replace	5%	\$59,443	North end of north west classrooms
A20 Basement Construction							,		400)	•
A2010 Basement I			None	Minor	Moderate	Major	Replace			
A2020 Basement \	Valls	0%	None	Minor	Moderate	Major	Replace	0%	\$0	
B SHELL		<u>'</u>								
<u>B10 Superstructure</u>				_			_	_		
B1010 Floor Const		0%	None	Minor	Moderate	Major	Replace	0%	\$0	
	Steel	0%	None	Minor	Moderate	Major	Replace	0%	\$0	North end of north west classrooms
B1020 Roof Const	Concrete Wood	100% 100%	None None	Minor Minor	Moderate Moderate	Major x Major	x Replace	5% 20%	\$118,885 \$68,370	North end of north west classicoms
B1020 ROOI COIISE	Steel	0%	None	Minor	Moderate	x Major Major	Replace Replace	0%	\$0	
	Concrete	0%	None	Minor	Moderate	Major	Replace	0%	\$0	
B20 Exterior Enclosure	25	370			oderate		периос		ΨΨ	1
B2010 Exterior Wa	alls Concrete Formed	d / Tilt 0%	None	Minor	Moderate	Major	Replace	0%	\$0	
	Masonry	0%	None	Minor	Moderate	Major	Replace	0%	\$0	
			П							Touch up paint needed in some areas at the
	Framed w/ Wood		None	Minor	x Moderate	Major	Replace	10%	\$13,773	bottom of siding, around doors.
	Framed w/Metal		None	Minor	Moderate	Major	Replace	0%	\$0	
	Framed w/Stucco		None	Minor	Moderate	Major	Replace	0%	\$0	
22222	Framed w/Masor		None	Minor	Moderate	Major	Replace	0%	\$0	
B2020 Exterior Wi		0%	None	Minor	Moderate	Major	Replace	0%	\$0	Donlare single page windows with double
	Aluminum/Steel Clad	100%	None None	Minor Minor	Moderate Moderate	Major Major	x Replace Replace	100% 0%	\$448,623 \$0	Replace single pane windows with double
	Curtain Wall	0%	None	Minor	Moderate	Major	Replace	0%	\$0	
	curtain waii	070	None	Willion	Wioderate	Iviajoi	Керівее	070	- - - - - - - - -	All wood veneer exterior doors have severe
B2030 Exterior Do	ors Wood	35	None	Minor	Moderate	Major	x Replace	100%	\$77,406	damage and the veneer is peeling off.
	Hollow Metal	0	None	Minor	Moderate	Major	Replace	0%	\$0	
_	Storefront	0	None	Minor	Moderate	Major	Replace	0%	\$0	
B30 Roofing	Anhalt Chinala	0%	None	Minor	Madarata	Major	Donlass	0%	ćo.	
B3010 Roof Cover	ings Asphalt Shingle Built-Up	0%	None None	Minor	Moderate Moderate	Major Major	Replace Replace	0%	\$0 \$0	
	Single Ply	0%	None	Minor	Moderate	Major	Replace	0%	\$0	
	Single 11,	070	H		- moderate	.v.ajo.	- Nepidee	070	Ŷ.	More investigation needed, Interior ceilings have
	Metal	100%	None	Minor	x Moderate	Major	Replace	60%	\$144,816	water damage.
	Concrete Tile	0%	None	Minor	Moderate	Major	Replace	0%	\$0	
B3020 Roof Openi	ngs Skylights	0%	None	Minor	Moderate	Major	Replace	0%	\$0	By Building GSF
	Access Hatch	0	None	Minor	Moderate	Major	Replace	0%	\$0	Per hatch
C INTERIORS										
C10 Interior Construction	France	4000/	T			N 4 - 1 - 1		00/	ćo.	
C1010 Partitions	Framed Masonry	100% 0%	x None None	Minor Minor	Moderate Moderate	Major Major	Replace Replace	0% 0%	\$0 \$0	
C1020 Interior Do		40	None	Minor	x Moderate	Major	Replace	50%	\$17,693	
CIOZO III EIIOI DOI	Hollow Metal	0	None	Minor	Moderate	Major	Replace	0%	\$17,093	
C4020 Fitting	NOT USED		None	Minor	Moderate	Major	Replace	0,0	Ÿ.	
C1030 Fittings	***************************************					,				
C1030 Fittings C20 Stairs										
	ruction Wood	0	None	Minor	Moderate	Major	Replace	0%	\$0	Cost/Flight
C20 Stairs	ruction Wood Metal	0	None None	Minor Minor	Moderate Moderate	Major Major	Replace Replace	0% 0%	\$0 \$0 \$0	Cost/Flight Cost/Flight

Physical Condition Assessment

	C2020 Chair Finish	Community Fill		٦,,,,,		Mandagata			I	00/	¢0	Cost/Elight
	C2020 Stair Finishes	Concrete Fill Resilient	0	None None	Minor Minor	Moderate Moderate	Major Major		Replace Replace	0% 0%	\$0 \$0	Cost/Flight Cost/Flight
C30 Into	erior Finishes	Nesilient	U	None	IVIIIIOI	Wioderate	iviajoi	Ш,	Kepiace	070	ŞŪ	COSCYTTIGHT
<u>e50 iiit</u>	C3010 Wall Finishes	Paint on Masonry	0%	None	Minor	Moderate	Major		Replace	0%	\$0	
		Wallboard	100%	_	Minor	Moderate	Major	-	Replace	0%	\$0	
		Wainscot	0%	None	Minor	Moderate	Major		Replace	0%	\$0	
		Ceramic Tile	0%	None	Minor	Moderate	Major		Replace	0%	\$0	
	C3020 Floor Finishes	Carpet / Soft Surface	0%	None	Minor	Moderate	Major		Replace	0%	\$0	
		Resilient Tile	80%	None	Minor	Moderate	Major	-	Replace	50%	\$122,025	Middle Quad of Classrooms West Wing
		Resilient Sheet	0%	None	Minor	Moderate	Major		Replace	0%	\$0	
		Polished Concrete	0%	None	Minor	Moderate	Major		Replace	0%	\$0	
		Ceramic Tile	4%	None	Minor	Moderate	Major	ХF	Replace	10%	\$4,511	Patch floor in restrooms converted to ADA
		Liquid Applied	0%	None	Minor	Moderate	Major	F	Replace	0%	\$0	
		Wood Sports Floor	16%	_	Minor	Moderate	Major		Replace	0%	\$0	
	C3030 Ceiling Finishes	Wallboard	0%	None	Minor	Moderate	Major		Replace	0%	\$0	
		Lay-In Ceiling Tile	0%	None	Minor	Moderate	Major		Replace	0%	\$0	
		Glued-Up Ceiling Tile	80%	None	Minor	Moderate	Major	_	Replace	50%	\$85,059	Water damage on a few tiles.
		Painted Structure	20%	None	Minor	Moderate	Major		Replace	0%	\$0	
D SERVICES												
D10 Co				٦					I	4000/	¢0	
	D1010 Elevators & Lifts D1020 Escalators & Moving Walks		0	None None	Minor Minor	Moderate Moderate	Major Major		Replace Replace	100% 100%	\$0 \$0	
	D1090 Other Conveying Systems		0	None	Minor	Moderate	Major		Replace	100%	\$0	
D20 Plu			U	None	IVIIIIOI	iviouerate	iviajoi	Ш'	neplace	100%	ŞÜ	
DZOFIU	mionig			1				П	ı			All (N) fixtures must meet ADA requirements by
	D2010 Plumbing Fixtures		100%	None	Minor	Moderate	Major	x F	Replace	100%	\$403,761	code.
	D2020 Domestic Water Distribution		100%	None	x Minor	Moderate	Major		Replace	100%	\$55,181	
	D2030 Sanitary Waste		100%	None	x Minor	Moderate	Major		Replace	100%	\$70,434	
	D2040 Rain Water Drainage		100%	x None	Minor	Moderate	Major		Replace	100%	\$0	Pitched roof with gutters & downspout.
	D2090 Other Plumbing Systems	NOT USED		None	Minor	Moderate	Major	F	Replace			
D30 HV	AC.						-					-
									_			
	D3010 Energy Supply		0%	None	Minor	Moderate	Major		Replace	0%	\$0	Diesel Piping
		Boiler	0% 100%	None None	Minor Minor	Moderate Moderate	Major x Major		Replace Replace	0% 100%	\$0 \$231,041	18 Year old equipment. Inefficient.
	D3010 Energy Supply	Boiler										18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement.
	D3010 Energy Supply		100%	None	Minor	Moderate	x Major	F	Replace	100%	\$231,041	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central
	D3010 Energy Supply	Air Handler	100%	None None	Minor	Moderate Moderate	x Major	F	Replace Replace	100%	\$231,041 \$64,871	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters
	D3010 Energy Supply	Air Handler Furnace	100% 60% 30%	None None None	Minor Minor Minor	Moderate Moderate x Moderate	x Major x Major Major	F	Replace Replace Replace	100% 100% 30%	\$231,041 \$64,871 \$5,410	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central
	D3010 Energy Supply D3020 Heat Generating Systems	Air Handler Furnace Heat Exchanger	60% 30% 0%	None None None None	Minor Minor Minor Minor	Moderate x Moderate Moderate Moderate	x Major x Major Major Major	F	Replace Replace Replace Replace	100% 100% 30% 0%	\$231,041 \$64,871 \$5,410 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters
	D3010 Energy Supply	Air Handler Furnace Heat Exchanger Component of air handler	60% 30% 0%	None None None None None	Minor Minor Minor Minor	Moderate x Moderate Moderate Moderate Moderate	x Major x Major Major Major Major Major	F F F F F F F F F F F F F F F F F F F	Replace Replace Replace Replace Replace	100% 100% 30% 0% 0%	\$231,041 \$64,871 \$5,410 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller	100% 60% 30% 0% 0%	None None None None None None	Minor Minor Minor Minor Minor Minor Minor	Moderate x Moderate Moderate Moderate Moderate Moderate Moderate	x Major x Major Major Major Major Major Major	F F F F F F F F F F F F F F F F F F F	Replace Replace Replace Replace Replace Replace	100% 100% 30% 0% 0%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters
	D3010 Energy Supply D3020 Heat Generating Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork	100% 60% 30% 0% 0% 0% 100%	None None None None None None None	Minor Minor Minor Minor Minor Minor Minor Minor Minor	Moderate x Moderate Moderate Moderate Moderate Moderate Moderate Moderate	x Major x Major Major Major Major Major Major Major Major	F F F F F F F F F F F F F F F F F F F	Replace Replace Replace Replace Replace Replace	100% 100% 30% 0% 0% 0% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$231,041	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply	100% 60% 30% 0% 0% 100% 0%	None None None None None None None None	Minor Minor Minor Minor Minor Minor Minor Minor Minor	Moderate x Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate	x Major x Major	F F F F F F F F F F F F F F F F F F F	Replace Replace Replace Replace Replace Replace Replace Replace Replace	100% 100% 30% 0% 0% 0% 100% 0%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$231,041 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork	100% 60% 30% 0% 0% 0% 100%	None None None None None None None	Minor Minor Minor Minor Minor Minor Minor Minor Minor	Moderate x Moderate Moderate Moderate Moderate Moderate Moderate Moderate	x Major x Major	F F F F F F F F F F F F F F F F F F F	Replace Replace Replace Replace Replace Replace Replace Replace Replace	100% 100% 30% 0% 0% 0% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$231,041	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit	100% 60% 30% 0% 0% 0% 100% 0% 0%	None None None None None None None None	Minor	Moderate x Moderate Moderate Moderate Moderate Moderate Moderate Moderate Moderate	x Major x Major	F F F F F F F F F F F F F F F F F F F	Replace	100% 100% 30% 0% 0% 0% 100% 0% 0%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit	100% 60% 30% 0% 0% 0% 100% 0% 50%	None None None None None None None None	Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor	Moderate x Moderate	x Major x Major	F F F F F F F F F F F F F F F F F F F	Replace Replace Replace Replace Replace Replace Replace Replace Replace	100% 100% 30% 0% 0% 0% 100% 0% 0% 50%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit	100% 60% 30% 0% 0% 0% 100% 50% 100%	None None None None None None None None	Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor Minor	Moderate x Moderate	x Major x Major	F F F F F F F F F F F F F F F F F F F	Replace	100% 100% 30% 0% 0% 0% 100% 0% 0% 50% 50%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit	100% 60% 30% 0% 0% 0% 100% 50% 100%	None None None None None None None None	Minor	Moderate x Moderate	x Major x Major		Replace	100% 100% 30% 0% 0% 100% 0% 50% 50% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping
<u>D40</u> Fin	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% 60% 30% 0% 0% 0% 100% 50% 100%	None None None None None None None None	Minor	Moderate x Moderate	x Major x Major		Replace	100% 100% 30% 0% 0% 00% 100% 0% 50% 50% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$1231,041 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping Split system cooling 2 - Central Quarters
<u>D40 Fir</u>	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment e Protection D4010 Sprinklers	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% 60% 30% 0% 0% 0% 100% 50% 100% 100%	None None None None None None None None	Minor	Moderate x Moderate	x Major x Major	F F F X F F X F F F F F F F F F F F F F	Replace	100% 100% 30% 0% 0% 100% 0% 50% 50% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping
<u>D40 Fir</u>	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment e Protection P4010 Sprinklers D4020 Standpipes	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% 60% 30% 0% 0% 0% 100% 50% 100% 100%	None None None None None None None None	Minor	Moderate x Moderate	x Major x Major	F F F F F F F F F F F F F F F F F F F	Replace	100% 100% 30% 0% 0% 00% 100% 0% 50% 50% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping Split system cooling 2 - Central Quarters
<u>D40 Fir</u>	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment e Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% 60% 30% 0% 0% 0% 100% 50% 100% 100%	None None None None None None None None	Minor	Moderate x Moderate	x Major x Major	F F F F F F F F F F F F F F F F F F F	Replace	100% 100% 30% 0% 0% 00% 100% 0% 50% 50% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping Split system cooling 2 - Central Quarters
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment e-Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% 60% 30% 0% 0% 0% 100% 50% 100% 100%	None None None None None None None None	Minor	Moderate x Moderate	x Major x Major	F F F F F F F F F F F F F F F F F F F	Replace	100% 100% 30% 0% 0% 00% 100% 0% 50% 50% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping Split system cooling 2 - Central Quarters
D40 Fire	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment e Protection D4010 Sprinklers D4030 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems ctrical	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% 60% 30% 0% 0% 0% 100% 50% 100% 100% 100%	None None None None None None None None	Minor	Moderate X Moderate	x Major x Major	F F F F F F F F F F F F F F F F F F F	Replace	100% 100% 30% 0% 0% 00% 100% 0% 50% 50% 100% 0%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$35,217 \$120,680 \$0 \$163,299 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping Split system cooling 2 - Central Quarters
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment e Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems ctrical D5010 Electrical Service & Distribution	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit	100% 60% 30% 0% 0% 0% 100% 50% 100% 100% 100% 100%	None None None None None None None None	Minor	Moderate x Moderate	x Major x Major	F	Replace	100% 100% 30% 0% 0% 100% 0% 100% 50% 100% 100% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$0 \$0 \$120,680 \$0 \$0 \$120,680 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping Split system cooling 2 - Central Quarters No Wet Pipe Spinkler System
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment e Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems ctrical D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit NOT USED	100% 60% 30% 0% 0% 0% 0% 100% 50% 100% 100% 100% 1	None None None None None None None None	Minor	Moderate x Moderate	x Major x Major		Replace	100% 100% 30% 0% 0% 0% 0% 0% 0% 0% 50% 50%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$10 \$231,041 \$0 \$0 \$0 \$0 \$0 \$35,217 \$120,680 \$0 \$0 \$163,299 \$0 \$0 \$0 \$0 \$0 \$246,294	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping Split system cooling 2 - Central Quarters
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment e Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems ctrical D5010 Electrical Service & Distribution	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit NOT USED NOT USED	100% 60% 30% 0% 0% 0% 100% 50% 50% 100% 100% 100%	None None None None None None None None	Minor Minor	Moderate x Moderate	x Major x Major		Replace	100% 100% 30% 0% 0% 0% 0% 0% 50% 50% 100% 0% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$35,217 \$120,680 \$0 \$0 \$0 \$163,299 \$0 \$0 \$0 \$246,294 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping Split system cooling 2 - Central Quarters No Wet Pipe Spinkler System
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment e Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems ctrical D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit NOT USED Voice / Data System Clock / Intercom System	100% 60% 30% 0% 0% 0% 100% 50% 50% 100% 100% 100%	None None None None None None None None	Minor Minor	Moderate x Moderate	x Major x Major Major		Replace	100% 100% 30% 0% 0% 0% 100% 50% 50% 100% 100% 100% 100% 100% 100% 100% 100% 100% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$35,217 \$120,680 \$0 \$0 \$0 \$0 \$163,299 \$0 \$0 \$0 \$0 \$44,862	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping Split system cooling 2 - Central Quarters No Wet Pipe Spinkler System
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment e Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems ctrical D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit NOT USED Voice / Data System Clock / Intercom System Closed Circuit Surveillance	100% 60% 30% 0% 0% 0% 100% 50% 50% 100% 100% 100%	None None None None None None None None	Minor Minor	Moderate x Moderate	x Major x Major		Replace	100% 100% 30% 0% 0% 0% 0% 0% 50% 50% 100% 0% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$35,217 \$120,680 \$0 \$0 \$0 \$163,299 \$0 \$0 \$0 \$246,294 \$0	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping Split system cooling 2 - Central Quarters No Wet Pipe Spinkler System Upgrade Fixtures to LED Replace and add to clock system
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment e Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems ctrical D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit NOT USED Voice / Data System Clock / Intercom System	100% 60% 30% 0% 0% 0% 0% 100% 50% 100% 100% 100% 1	None None None None None None None None	Minor	Moderate X Moderate	x Major x Major Major	F	Replace	100% 100% 30% 0% 0% 0% 100% 0% 100% 100%	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$35,217 \$120,680 \$0 \$0 \$0 \$0 \$246,294 \$0 \$44,862 \$55,181	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping Split system cooling 2 - Central Quarters No Wet Pipe Spinkler System Upgrade Fixtures to LED Replace and add to clock system Replace and add to Camera System
	D3010 Energy Supply D3020 Heat Generating Systems D3030 Cooling Generating Systems D3040 Distribution Systems D3050 Terminal & Package Units D3060 Controls & Instrumentation D3070 Systems Testing & Balancing D3090 Other HVAC Systems & Equipment e Protection D4010 Sprinklers D4020 Standpipes D4030 Fire Protection Specialties D4090 Other Fire Protection Systems ctrical D5010 Electrical Service & Distribution D5020 Lighting and Branch Wiring	Air Handler Furnace Heat Exchanger Component of air handler Stand alone chiller Ductwork Hot water return & supply Above ceiling VAV unit In-room ventilator unit In-room radiant unit NOT USED Voice / Data System Clock / Intercom System Closed Circuit Surveillance Access Control System	100% 60% 30% 0% 0% 0% 0% 100% 50% 100% 100% 100% 1	None None None None None None None None	Minor	Moderate x Moderate	x Major x Major	F	Replace	100% 100% 30% 0% 0% 0% 0% 100% 0% 100% 10	\$231,041 \$64,871 \$5,410 \$0 \$0 \$0 \$0 \$231,041 \$0 \$0 \$0 \$0 \$0 \$120,680 \$0 \$0 \$120,680 \$0 \$0 \$0 \$140,299 \$0 \$0 \$246,294 \$0 \$0 \$44,862 \$555,181 \$44,862	18 Year old equipment. Inefficient. No outside air. Dosen't meet code requirement. Not efficient. Split system cooling 2-central quarters 2 - Gymnasium H&V Units Steam Piping Split system cooling 2 - Central Quarters No Wet Pipe Spinkler System Upgrade Fixtures to LED Replace and add to clock system Replace and add to Camera System No Access Control System in place

Physical Condition Assessment

D5090 Other Electrical Systems	Lighting Control System NOT USED	100% None	Minor	Moderate Moderate	Major Major	x Replace	100%	\$37,684	No Lighting Control System
·					.,.				
E EQUIPMENT & FURNISHINGS									
E10 Equipment	Food Service	0% None	Minor	Moderate	Major	Replace	0%	\$0	
E1010 Commercial Equipment	Vocational	0% None	Minor	Moderate	Major	Replace	0%	\$0	
E1020 Institutional Equipment	Science	0 None	Minor	Moderate	Major	Replace	0%	\$0	_
E1020 Ilistitutional Equipment	Art	0 None	Minor	Moderate	Major	Replace	0%	\$0	
	Stage Performance	0 None	Minor	Moderate	Major	Replace	0%	\$0	Cost/SF of Stage Performance Area
	Restroom Accessories/Stalls	0% None	Minor	Moderate	Major	Replace	0%	\$0	
E1030 Vehicular Equipment	NOT USED	None	Minor	Moderate	Major	Replace	4,1	7-5	
E1090 Other Equipment	NOT USED	None	Minor	Moderate	Major	Replace			
E20 Furnishings									_
E2010 Fixed Furnishings		100% None	Minor	x Moderate	Major	Replace	100%	\$105,426	
E2020 Movable Furnishings		100% x None	Minor	Moderate	Major	Replace	0%	\$0	
F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED				_					
G BUILDING SITE WORK	NOTUSES								
G10 Site Preparation	NOT USED								
G20 Site Improvements				No. de unte			00/	ćo	Cont ICE of works and a
G2010 Roadways		0 None 22500 None	Minor Minor	Moderate Moderate	Major x Major	Replace Replace	0% 100%	\$0 \$161,723	Cost/SF of surface area Cost/SF of surface area
G2020 Parking Lots G2030 Pedestrian Paving		8400 None	Minor	Moderate	x Major x Major	Replace	50%	\$41,799	Playground AC - 4 Square & Basketball
G2040 Site Development		1850 None	Minor	Moderate	x Major	Replace	10%	\$1,637	Flayground AC - 4 Square & Basketball
G2050 Landscaping		98000 None	Minor	Moderate	Major	Replace	0%	\$0	Cost/SF of irrigated area
G30 Site Mechanical Utilities		30000 None	Willion	Wioderate	iviajoi	перисс	070	ÇÜ	cost/si of irrigated area
G3010 Water Supply	Domestic	125 None	Minor	Moderate	Major	Replace	0%	\$0	Exterior
,	Fire	0 None	Minor	Moderate	Major	Replace	0%	\$0	Exterior
G3020 Sanitary Sewer		125 None	Minor	Moderate	Major	Replace	0%	\$0	Exterior
G3030 Storm Sewer		128900 None	Minor	x Moderate	Major	Replace	35%	\$149,665	Unknown System
G3040 Heating Distribution		0 None	Minor	Moderate	Major	Replace	0%	\$0	Enter LF of pipe in cell E147
G3050 Cooling Distribution		0 None	Minor	Moderate	Major	Replace	0%	\$0	Enter LF of pipe in cell E148
G3060 Fuel Distribution		0 None	Minor	Moderate	Major	Replace	0%	\$0	Enter LF of pipe in cell E149
G3090 Other Site Mechanical Utilities	NOT USED	None	Minor	Moderate	Major	Replace			
G40 Site Electrical Utilities				_		_			
G4010 Electrical Distribution	Service	0% None	Minor	Moderate	Major	Replace	0%	\$0	
	Generator	0% None	Minor	Moderate	Major	Replace	0%	\$0	
G4020 Site Lighting		0% None	Minor	Moderate	Major	Replace	0%	\$0	
G4030 Site Communications & Security	NOTUCED	0% None	Minor	Moderate	Major	Replace	0%	\$0	
G4090 Other Site Electrical Utilities G90 Other Site Construction	NOT USED NOT USED	None	Minor	Moderate	Major	Replace			
350 Other Site Constitution	NOT USED								
OTHER									
				Unit of		Unit			
Description of System				Measure	Quantity	Budget		Extended	Notes
								\$0)
			· · · · · · · · · · · · · · · · · · ·					\$(
								\$0	
				→ 			_	\$0	
				_		4		\$0	
				⊣		┩ ┡───	-	\$(
						J		\$0	<u> </u>

\$3,558,977
\$1,352,411
\$4,911,388
\$5,598,983
\$5,822,942
\$6,055,860

Replacement Budget

\$20,743,035

Inflation Assigned for a 30-month period assuming 1 year till bond **District Name:** John Day SD 3 State Assigned Inflation Factor 1.14 and 1-1/2 years into a 3-year design/construction cycle cost estimating, etc.), state solar, permits, survey, geo, bond Site Name: **Humbolt Elementary School** State Assigned Soft Development Factor 1.38 issuance, management, furnishings, and 15% contingency **Building Name: Humbolt Elementary School Escalation Beyond 30 months** 1.04 Inflation Rate Per Annum for Projects commencing after June 2021 **Building ID:** 20080100

				LEVEL OF ACTION							
Level 1	Level 2	Level 3	Type (as applicable)		Minor		Moderate		Major		Replace as part of Renovation
A SUBS	TRUCTUE	RE	, , , , ,					•			•
	A10 Four	<u>ndations</u>									
		A1010 Standard Foundations		\$0.50	Minor		Moderate	\$27.68	Major		Replace
		A1020 Special Foundations		\$0.50	Minor		Moderate	\$35.28	Major		Replace
		A1030 Slab on Grade			Minor	\$2.13	Moderate	\$26.50	Major		Replace
	A20 Base	ement Construction			- -				- -		-
		A2010 Basement Excavation	NOT USED		Minor		Moderate		Major		Replace
		A2020 Basement Walls		\$0.67	Minor	\$2.13	Moderate	\$8.96	Major		Replace
B SHEL	L										
	<u>B10 Supe</u>	<u>erstructure</u>			_	-	•	Ē	_	_	_
		B1010 Floor Construction	Wood		Minor	\$6.72	Moderate		Major	\$43.00	Replace
			Steel		Minor		Moderate		Major	\$47.00	Replace
			Concrete		Minor	\$14.00	Moderate		Major	\$53.00	Replace
		B1020 Roof Construction	Wood		Minor		Moderate	\$7.62	Major	\$33.00	Replace
			Steel		Minor		Moderate	\$9.41	Major	\$37.00	Replace
			Concrete		Minor		Moderate	\$15.68	Major	\$43.00	Replace
	B20 Exte	rior Enclosure			•				•		•
		B2010 Exterior Walls	Concrete Formed / Tilt		Minor		Moderate	\$4.70	Major		Replace
			Masonry		Minor		Moderate	\$6.72	Major	\$32.73	Replace
			Framed w/ Wood Siding		Minor	\$3.07	Moderate	\$5.82	Major	\$25.51	Replace
			Framed w/ Metal Panel		Minor	\$3.57	Moderate	\$6.82	Major	\$30.51	Replace
			Framed w/Stucco		Minor	\$3.07	Moderate	\$5.82	Major	\$30.69	Replace
			Framed w/Masonry Veneer		Minor	\$2.46	Moderate	\$4.48	Major	\$38.61	Replace
		B2020 Exterior Windows	Wood		Minor	\$2.69	Moderate	\$4.82	Major	\$9.30	Replace
			Aluminum		Minor	\$2.69	Moderate	\$3.81	Major	\$10.00	Replace
			Clad		Minor	\$2.69	Moderate	\$4.14	Major	\$9.50	Replace
			Curtain Wall		Minor	\$1.68	Moderate	\$3.02	Major	\$28.00	Replace
		B2030 Exterior Doors	Wood		Minor	\$1,000.00	Moderate	\$1,500.00	Major	\$2,000.00	Replace
			Hollow Metal		Minor	· ·	Moderate	\$1,300.00	Major	\$1,800.00	Replace
			Storefront		Minor	\$1,200.00	Moderate	\$2,400.00	Major	\$3,000.00	Replace
	B30 Root				•				•		•
		B3010 Roof Coverings	Asphalt Shingle	\$1.35	Minor	-	Moderate	\$10.75	Major	\$15.00	Replace
			Built-Up	\$1.57	Minor	\$3.98	Moderate	\$11.76	Major	\$26.00	Replace
			Single Ply	\$2.35	Minor	\$4.26	Moderate	\$11.31	Major	\$24.00	Replace

PCA Cost Tables - READ ONLY

		Metal Concrete Tile		inor \$5.38		Major		Replace Replace
D	33020 Roof Openings	Skylights		inor \$0.10		Major Major		Replace
Ь	3020 Roof Openings	Access Hatch		inor	Moderate	Major		Replace
C INTERIORS		Access Hatch	IVI	IIIOI	Woderate	Iviajoi	\$3,300.00	срівсе
	r Construction							
	1010 Partitions	Framed	M	inor	Moderate	Major	\$15.68 R	Replace
		Masonry	M	inor	Moderate	\$6.94 Major		Replace
C	1020 Interior Doors	Wood	M	inor \$800.0	00 Moderate	\$1,300.00 Major		Replace
		Hollow Metal	M	inor \$800.0	00 Moderate	\$1,100.00 Major	\$1,600.00 R	Replace
C	1030 Fittings	NOT USED	M	inor	Moderate	Major	P	Replace
C20 Stairs								
C	2010 Stair Construction	Wood	M	inor	Moderate	\$5,000.00 Major	\$25,000.00 R	Replace
		Metal	\$1,500.00 M	inor	Moderate	\$5,000.00 Major	\$30,000.00 R	Replace
		Concrete	М	inor	Moderate	\$7,500.00 Major	\$35,000.00 R	Replace
C	2020 Stair Finishes	Concrete Fill	\$1,000.00 M	inor	Moderate	Major	\$5,000.00 R	Replace
		Resilient	M	inor	Moderate	Major	\$2,500.00 R	Replace
C30 Interio	<u>r Finishes</u>							
C	3010 Wall Finishes	Paint on Masonry	\$2.24 M	inor	Moderate	Major	\$4.37 R	Replace
		Wallboard	\$2.02 M	inor \$2.46	Moderate	Major	\$8.06 R	Replace
		Wainscot	\$2.02 M	inor	Moderate	Major	\$1.34 R	Replace
		Ceramic Tile	\$0.90 M	inor	Moderate	Major	\$2.43 R	Replace
C	3020 Floor Finishes	Carpet / Soft Surface	M	inor	Moderate	Major	\$6.68 R	Replace
		Resilient Tile	\$1.01 M	inor	Moderate	\$4.76 Major	\$6.80 R	Replace
		Resilient Sheet	M	inor	Moderate	Major	\$12.00 R	Replace
		Polished Concrete	\$2.02 M	inor	Moderate	Major	\$9.00 R	Replace
		Ceramic Tile	\$3.81 M	inor	Moderate	Major	\$25.14 R	Replace
		Liquid Applied	M	inor	Moderate	Major	\$14.11 R	Replace
		Wood Sports Floor	M	inor \$7.00) Moderate	Major	\$18.00 R	Replace
C	3030 Ceiling Finishes	Wallboard	\$3.14 M	inor \$7.00) Moderate	Major	\$12.00 R	Replace
		Lay-In Ceiling Tile		inor \$1.39	Moderate	Major		Replace
		Glued-Up Ceiling Tile	\$0.65 M	inor	Moderate	Major		Replace
		Painted Structure	M	inor	Moderate	Major	\$3.21 R	Replace
D SERVICES								
D10 Conve			44.700	. 47.64		444.000	454 400 F	
	01010 Elevators & Lifts			inor \$7,61		\$14,280 Major		Replace
	01020 Escalators & Moving Walks			inor \$9,63		Major		Replace
	01090 Other Conveying Systems		IVI	inor \$3,80	8 Moderate	Major	\$25,000 R	Replace
D20 Plumb			D.4	: 61.40	Madausta	Maian	¢0.00	
	22010 Plumbing Fixtures			inor \$1.40		Major		Replace
	22020 Domestic Water Distribution			inor \$1.68		Major		Replace
	02030 Sanitary Waste			inor \$1.01	Moderate Moderate	Major		Replace
	22040 Rain Water Drainage	NOT LISED				Major		Replace
	22090 Other Plumbing Systems	NOT USED	IVI	inor	Moderate	Major	R	Replace
D30 HVAC								

State of Oregon School Facilities Assessment Template 5/1/2019

PCA Cost Tables - READ ONLY

D0040 5		44.00			40.74
D3010 Energy Supply		\$1.23 Minor	Moderate	Major	\$2.74 Replace
D3020 Heat Generating Systems	Boiler	\$2.02 Minor	\$2.58 Moderate	\$5.15 Major	\$9.52 Replace
	Air Handler	Minor	Moderate	\$2.41 Major	\$5.82 Replace
	Furnace	Minor	\$1.34 Moderate	\$2.46 Major	\$4.26 Replace
	Heat Exchanger	Minor	\$0.56 Moderate	\$1.01 Major	\$2.02 Replace
D3030 Cooling Generating Systems	Component of air handler	Minor	Moderate	\$2.41 Major	\$3.86 Replace
	Stand alone chiller	Minor	Moderate	Major	\$5.54 Replace
D3040 Distribution Systems	Ductwork	Minor	\$1.79 Moderate	\$2.13 Major	\$5.15 Replace
	Hot water return & supply	\$1.23 Minor	\$1.68 Moderate	Major	\$8.57 Replace
D3050 Terminal & Package Units	Above ceiling VAV unit	Minor	Moderate	Major	\$4.03 Replace
	In-room ventilator unit	Minor	\$5.38 Moderate	Major	\$15.96 Replace
	In-room radiant unit	\$1.23 Minor	Moderate	Major	\$3.14 Replace
D3060 Controls & Instrumentation		Minor	Moderate	\$0.56 Major	\$2.69 Replace
D3070 Systems Testing & Balancing		Minor	Moderate	Major	\$1.46 Replace
D3090 Other HVAC Systems & Equipment	: NOT USED	Minor	Moderate	Major	Replace
<u>D40 Fire Protection</u>					
D4010 Sprinklers		Minor	\$1.01 Moderate	Major	\$3.64 Replace
D4020 Standpipes		Minor	\$1.38 Moderate	Major	\$2.24 Replace
D4030 Fire Protection Specialties		Minor	\$8.81 Moderate	Major	\$33.15 Replace
D4090 Other Fire Protection Systems	NOT USED	Minor	Moderate	Major	Replace
D50 Electrical					
D5010 Electrical Service & Distribution		Minor	\$3.58 Moderate	\$6.27 Major	\$8.11 Replace
D5020 Lighting and Branch Wiring		Minor	Moderate	\$5.49 Major	\$18.00 Replace
D5030 Communications & Security	Voice / Data System	Minor	\$0.35 Moderate	\$0.73 Major	\$3.64 Replace
	Clock / Intercom System	Minor	\$0.12 Moderate	\$0.28 Major	\$1.00 Replace
	Closed Circuit Surveillance	Minor	\$0.16 Moderate	\$0.34 Major	\$1.23 Replace
	Access Control System	Minor	\$0.11 Moderate	\$0.25 Major	\$1.00 Replace
	Intrusion Alarm System	Minor	\$0.07 Moderate	\$0.16 Major	\$0.73 Replace
	Fire Alarm / Detection	Minor	\$0.22 Moderate	\$0.47 Major	\$2.13 Replace
	Lighting Control System	\$0.11 Minor	Moderate	\$0.25 Major	\$0.84 Replace
D5090 Other Electrical Systems	NOT USED	Minor	Moderate	Major	Replace
,					
E EQUIPMENT & FURNISHINGS					
E10 Equipment					
E1010 Commercial Equipment	Food Service	\$0.45 Minor	\$0.73 Moderate	\$0.90 Major	\$2.35 Replace
	Vocational	\$0.45 Minor	Moderate	\$0.92 Major	\$2.16 Replace
E1020 Institutional Equipment	Science	Minor	\$1.46 Moderate	\$1.81 Major	\$3.96 Replace
	Art	Minor	\$1.57 Moderate	\$1.68 Major	\$3.81 Replace
	Stage Performance	Minor	\$12 Moderate	\$25 Major	\$60 Replace
	Restroom Accessories/Stalls	\$0.22 Minor	\$1.27 Moderate	\$0.39 Major	\$1.98 Replace
E1030 Vehicular Equipment	NOT USED	Minor	Moderate	Major	Replace
E1090 Other Equipment	NOT USED	Minor	Moderate	Major	Replace
E20 Furnishings				-	
E2010 Fixed Furnishings		\$1.39 Minor	\$2.35 Moderate	\$3.74 Major	\$9.32 Replace
E2020 Movable Furnishings		Minor	Moderate	Major	\$24.00 Replace
ŭ					

F SPECIAL CONSTRUCTION & DEMOLITION - NOT USED

DING SITE WORK						
G10 Site Preparation	NOT USED					
G20 Site Improvements						_
G2010 Roadways		\$1.57 Mino	Moderate	\$6.50 Maj	jor \$8.00	Replace
G2020 Parking Lots		\$1.57 Mino	Moderate	\$6.50 Maj	jor \$8.00	Replace
G2030 Pedestrian Paving		Mino	Moderate	\$9.00 Maj	jor \$11.00	Replace
G2040 Site Development		Mino	Moderate	\$8.00 Maj	jor \$35.00	Replace
G2050 Landscaping		Mino	Moderate	Maj	jor \$2.50	Replace
G30 Site Mechanical Utilities					·	_
G3010 Water Supply	Domestic	Mino	Moderate	Maj	jor \$65.00	Replace
	Fire	Mino	Moderate	Maj	jor \$65.00	Replace
G3020 Sanitary Sewer		Mino	Moderate	Maj	jor \$45.00	Replace
G3030 Storm Sewer		\$2.00 Mino	r \$3.00 Moderate	\$4.00 Maj	jor \$7.00	Replace
G3040 Heating Distribution		Mino	Moderate	Maj	jor \$225.00	Replace
G3050 Cooling Distribution		Mino	Moderate	Maj	jor \$225.00	Replace
G3060 Fuel Distribution		Mino	Moderate	Maj	jor \$35.00	Replace
G3090 Other Site Mechanical Utilities	NOT USED	Mino	Moderate	Maj	jor	Replace
G40 Site Electrical Utilities						
G4010 Electrical Distribution	Service	Mino	Moderate	\$0.81 Ma	jor \$2.48	Replace
	Generator	\$2,000.00 Mino	s \$10,000.00 Moderate	\$30,000.00 Maj	jor \$30,000.0	O Replace
G4020 Site Lighting		Mino	r \$0.73 Moderate	Maj	jor \$1.30	Replace
G4030 Site Communications & Security		Mino	Moderate	Maj	jor \$0.80	Replace
G4090 Other Site Electrical Utilities	NOT USED	Mino	Moderate	Maj	jor	Replace
G90 Other Site Construction	NOT USED					

Budgeted Replacement Cost of Buildings by Type

	Raw Budget / SF (as	Inflated Based on	<u>Developed</u>	Forwarded FCI
<u>Type</u>	of 1/31/19)	State Rate	Budget*	<u>Budget</u>
Elementary School	\$325 / SF	\$370.50	\$511 / SF	511.29
Middle School	\$340 / SF	\$387.60	\$535 / SF	0
K-8 School	\$360 / SF	\$410.40	\$566 / SF	0
High School	\$375 / SF	\$427.50	\$590 / SF	0
Gymnasium Building	\$430 / SF	\$490.20	\$676 / SF	0
Pool Building	\$532 / SF	\$606.48	\$837 / SF	0
Vocational Building	\$403 / SF	\$459.42	\$634 / SF	0
Administrative Building	\$320 / SF	\$364.80	\$503 / SF	0
Maintenance Building	\$405 / SF	\$461.70	\$637 / SF	0
Storage Building	\$305 / SF	\$347.70	\$480 / SF	0
Warehouse	\$305 / SF	\$347.70	\$480 / SF	0
Food Services Building	\$475 / SF	\$541.50	\$747 / SF	0
Bus Shelter	\$290 / SF	\$330.60	\$456 / SF	0
Bus Garage	\$305 / SF	\$347.70	\$480 / SF	0
Athletic Grandstand	\$270 / SF	\$307.80	\$425 / SF	0
Large Greenhouse	\$325 / SF	\$370.50	\$511 / SF	0
Other Commercial	\$336 / SF	\$383.04	\$529 / SF	0
			FCI Reference	511.29

^{*}Developed Budget is based on State Assigned factor on PSA Cost Table Sheet

Note:

Small support out buildings shall be assessed as "other" under the primary building assessment and not as their own building assessment

Assumed raw budgets are extrapolated from RLB Cost Estimating Guide and recent public bid results

County Cost Factor for Physical Assessment Budget Calculation

	Prevailing		
	Wage Rate		<u>Forwarded</u>
<u>Counties</u>	<u>Regions</u>	Cost Factor	<u>Factor</u>
Clatsop	1	1.05	0.00
Columbia	1	1.05	0.00
Tillamook	1	1.05	0.00
Clackamas	2	1.13	0.00
Multnomah	2	1.13	0.00
Washington	2	1.13	0.00
Marion	3	1.00	0.00
Polk	3	1.00	0.00
Yamhill	3	1.00	0.00
Benton	4	1.00	0.00
Lincoln	4	1.00	0.00
Linn	4	1.00	0.00
Lane	5	1.00	0.00
Douglas	6	0.98	0.00
Coos	7	0.98	0.00
Curry	7	0.98	0.00
Jackson	8	0.98	0.00
Josephine	8	0.98	0.00
Hood River	9	1.05	0.00
Sherman	9	1.05	0.00
Wasco	9	1.05	0.00
Crook	10	0.98	0.00
Deschutes	10	0.98	0.00
Jefferson	10	0.95	0.00
Klamath	11	0.95	0.00
Lake	11	0.95	0.00
Gilliam	12	0.97	0.00
Grant	12	0.97	0.97
Morrow	12	0.97	0.00
Umatilla	12	0.97	0.00
Wheeler	12	0.97	0.00
Baker	13	0.99	0.00
Union	13	0.99	0.00
Wallowa	13	0.99	0.00
Harney	14	0.91	0.00
Malheur	14	0.91	0.00
	Se	lected Factor	0.97

NOTES

Regions established by the State of Oregon BOLI Office

Relational rates between regions extrapolated from the National Building Cost Manual (2018)

Renovations, Additions & Prtbls

A. RENOVATIONS				
Renovation Number	Date	Construction Type	Square Footage	Usage
none				

B. ADDITIONS				
Addition Number	Date	Construction Type	Square Footage	Usage
1	1955	Wood Framed	10,672	Classrooms
2	1972	Wood Framed	4,956	Classrooms Add
3	1988	Wood Framed	3,186	Kindergarten Classrooms

C. PORTABLE CLASSROOMS				
Portable Number	Date Placed on Site	Age of Portable	Square Footage	Notes
1	Unknown		2,000	Computer Lab 1 and 2
2	Unknown		2,000	Choir and Music

SCHOOL SAFETY AUDIT ASSESSMENT					
	YES	NO	N/A	COMMENTS	
School grounds are fenced.	х			Partially Complete	
There is one clearly marked and designated entrance for visitors		х			
Signs are posted for visitors to report to main office through a designated entrance.	х				
Restricted areas are clearly marked		х			
Shrubs and foliage are trimmed to allow for good line of sight. (3'-0"/8'- 0" rule)	х				
Shrubs near building have been trimmed "up" to allow view of bottom of building			х		
Bus loading and drop-off zones are clearly defined.	х				
There is a schedule for maintenance of:					
a. Outside lights		х			
b. Locks/Hardware		х			
c. Storage Sheds	х				
d. Windows	х				
e. Other exterior buildings		х		Reporting Only	
Parent drop-off and pick-up area is clearly defined.		х			
There is adequate lighting around the building.		x			
Lighting is provided at entrances and other points of possible intrusion.		х			
The school ground is free from trash or debris.	x				
The school is free of graffiti.	x				
Play areas are fenced.	x				
Playground equipment has tamper-proof fasteners		х			
Visual surveillance of bicycle racks from main office is possible.	x	^			
	x				
Visual surveillance of parking lots from main office is possible	^	v			
Parking lot is lighted properly and all lights are functioning		X		Installed Company on wated	
Accessible lenses are protected by some unbreakable material		X		Installed Cameras are rated	
Staff and visitor parking has been designated		х			
Outside hardware has been removed from all doors except at points of entry.	х				
Ground floor windows:					
a. have no broken panes;	х			2001	
b. locking hardware is in working order.	х			80%	
Basement windows are protected with grill or well cover.			Х		
Doors are locked when classrooms are vacant.	Х				
High-risk areas are protected by high security locks and an alarm system		х			
a. Main office		х			
b. Cafeteria		х			
c. Computer Labs		х			
d. Industrial Arts rooms		х			
e. Science labs		х			
f. Nurses Office		х			
g. Boiler Room		х			
h. Electrical Rooms		х			
i. Phone line access closet		х			
Unused areas of the school can be closed off during after school activities.	х				
There is two-way communication between the main office and:					
a. Classroom	х				
b. Duty stations			х		
c. Re-locatable classrooms	х				
d. Staff and faculty outside building		х			
e. Buses	х				
There is a central alarm system in the school. If yes, briefly describe:		х			
The main entrance is visible from the main office.	х				

ADA ASSESSMENT					
	YES	NO	N/A	COMMENTS	
There is at least 1 route from site arrival points that does not require the use of stairs.	х				
If parking is provided for the public, there are adequate number of accessible spaces	х				
provide (1 per 25).					
There is at least 1 van accessible parking space among the accessible spaces.					
The slope of the accessible parking spaces and access aisles is no steeper than 1:48 in					
all directions.					
The access aisles adjoin an accessible route.	х				
Accessible spaces are identified with a sign that includes the International Symbol of				The Symbol was painted on the	
Accessibility.				pavement but don't remember if there were signs on posts.	
There are signs reading "van accessible" at van accessible spaces.		х			
If the accessible route crosses a curb, there is a curb ramp.			х	All even ground	
Ramps are sloped no greater than 1:12.			х		
The main entrance is accessible.	х				
If the main entrance is not accessible, there is an alternative accessible entrance.			х		
The alternative accessible entrance can be used independently and during the same			х		
hours as the main entrance.					
All inaccessible entrances have signs with the International Symbol of Accessibility	х				
indicating the location of the nearest accessible entrance.					
The door is equipped with hardware, including locks, that is operable with one hand	х				
and does not require tight grasping, pinching, or twisting of the wrist.					
The operable parts of the door hardware are no less than 34" and no greater than 48"	х				
above the floor or ground surface.					
In locker rooms, there is at least one room with a bench.	х				
At least one toilet room is accessible (either one for each sex or one unisex).	х				
There are signs with the International Symbol of Accessibility at inaccessible toilet	х				
rooms that give directions to accessible toilet rooms.					
There is a route to the accessible toilet room(s) that does not include stairs.	х				
The door is equipped with hardware that is operable with one hand and does not	х				
require tight grasping, pinching, or twisting of the wrist.					
The operable parts of the door hardware are no less than 34" and no greater than 48"	х				
above the floor or ground surface.					
The door can be opened easily (5 lbs. maximum force).	х				
Lighting controls are operable with one hand and without tight grasping, pinching, or	х				
twisting of the wrist.					
Mounted switches are no less than 34" and no greater than 48" above the floor or	х				
ground surface.					

INFORMATION TECHNOLOGY ASSESSMENT					
	YES	NO	N/A	COMMENTS	
1. Connectivity "speed " to the Facility:					
a. 10 Gbps or greater					
b. 1 Gbps or greater					
c. 100 Mbps or less	х				
d. 10 Mbps or less					
e. Less than 10 Mbps					
2. Local area network connectivity "speed " at the individual building level:					
a. 10 Gbps or greater					
b. 1 Gbps or greater	х				
c. 100 Mbps or less					
d. 10 Mbps or less					
e. Less than 10 Mbps					
3. Wireless Coverage:					
a. Facility Wide	х				
b. Secure?	х				
c. Type:					
i. AC					
ii. N					
iii. A/B/G	х				
4. Building cabling:					
a. Fiber (to the desktop)					
b. CAT 6					
c. CAT 5 E	х				
d. CAT 5					
5. Security:					
a. Access control					
b. Video Surveillance	х				
c. Central Communications Systems	х			phone system only	

	YES	NO	N/A	COMMENTS
Lead			-	
Has your facility been assessed for lead? If so when?		Х		
Is there lead in your facility?		Х		
Is lead abatement included in your future bond plans?		х		
Asbestos				
Has your facility been assessed for asbestos? If so when?		Х		
Is there asbestos in your facility?		Х		
Is asbestos abatement included in your future bond plans?		х		
Mold				
Has your facility been assessed for mold? If so when?		Х		
Is there mold in your facility?		Х		
Is mold abatement included in your future bond plans?		Х		
Water Quality				
Has your facility been assessed for water quality (lead, etc)? If so when?	х			2015, or more recently
Is there a water quality concern in your facility?		Х		
Is water treatment included in your future bond plans?		х		
PCBs				
Has your facility been assessed for PCBs? If so when?		Х		
Are there PCBs in your facility?		х		
Is PCB abatement included in your future bond plans?		х		
Radon				
Has your facility been assessed for Radon? If so when?		Х		
Is there Radon in your facility?		Х		
Is Radon management included in your future bond plans?	х			

INDOOR AIR QUALITY ASSESSMENT					
	YES	NO	N/A	COMMENTS	
Is someone designated to develop and implement an indoor air quality management		х			
plan for your school district?					
Does your district have an indoor air quality management plan that includes steps for		х			
preventing and resolving indoor air quality problems?					
Are school buildings inspected once or twice each year for conditions that may lead to		х			
indoor air quality problems?					
Is a preventive maintenance schedule established and in operation for the heating,	Х				
ventilation, and air conditioning (HVAC) system? Is the schedule in accordance with the					
manufacturer's recommendations or accepted practice for the HVAC system?					
Does the HVAC preventive maintenance schedule include the following?: checking			х		
and/or changing air filters and belts, lubricating equipment parts, checking the motors,					
and confirming that all equipment is in operating order.					
Is the maintenance schedule updated to show all maintenance performed on the	х				
building systems?					
Does the maintenance schedule include the dates that the building systems	х				
maintenance was performed and the names of the persons or companies performing					
the work?					
Are maintenance schedules retained for at least three years?	х				
Are damaged or inoperable components of the HVAC system replaced or repaired as	х				
appropriate?					
Are reservoirs or parts of the HVAC system with standing water checked visually for			х		
microbial growth?					
Are water leaks that could promote growth of biologic agents promptly repaired?			х		
Are damp or wet materials that could promote growth of biologic agents promptly	х				
dried, replaced, removed, or cleaned?					
Are microbial contaminants removed from ductwork, humidifiers, other HVAC and			х		
building system components, and from building surfaces such as carpeting and ceiling					
tiles when found during regular or emergency maintenance activities or visual					
inspection?					
Is general or local exhaust ventilation used where housekeeping and maintenance	х				
activities could reasonably be expected to result in exposure to hazardous substances					
above applicable exposure limits?					
Does the HVAC system have CO2 monitoring capability (demand control ventilation)?		х			
Are humidity levels maintained between 30% to 60% relative humidity?		х			
When a contaminant is identified in the make-up air supply, is the source of the			x		
contaminant eliminated, or are the make-up inlets or exhaust air outlets relocated to					
avoid entry of the contaminant into the air system?					
If buildings do not have mechanical ventilation, are windows, doors, vents, stacks, and	х				
other portals used for natural ventilation operating properly?					

Cell: C10

Comment: Standard spread and strip / perimeter footings; Apply rates to bldg footprint area

Cell: H10

Comment: Minor cracking observed - fill and seal the cracks to prevent water intrusion

Cell: L10

Comment: Settlement observed in surrounding conditions - requiring stabilization of the foundation, sub-grade adjustment, and re-enforcement of the

foundation Cell: C11

Comment: Pilings or other extended foundation systems that overcome non-standard soil conditions; Apply rates to bldg footprint area

Cell: H11

Comment: Minor cracking observed - fill and seal the cracks to prevent water intrusion

Cell: L11

Comment: Settlement observed in surrounding conditions - requiring stabilization of the foundation, sub-grade adjustment, and re-enforcement of the

foundation Cell: C12

Comment: Standard ground-set concrete slab. If slab is elevated (i.e. has a crawl space or basement), apply conditions to B1010 instead; Apply rates to bldg

footprint area

Cell: J12

Comment: Separation cracks occurring requiring route and fill and patch

Cell: L12

Comment: Differential settlement occurring - requires removal of section of slab, adjustment to sub-grade, and new infill

Comment: Assumed as concrete walls with water-proofing on the exterior. Includes only the structural portion and not the wall finishes; Apply to wall surface

area Cell: H15

Comment: Inadequate below grade venting is observed - cut in and add venting

Comment: Wall is cracked and spalling requiring route and fill and patch and re-finish

Cell: L15

Comment: Wall is cracked with evidence of water intrusion. Repairs to be implemented and water barrier to be applied to be applied

Cell: C18

Comment: A suspended floor including the structural members and floor construction, but not including the actual finish

Cell: J18

Comment: Deck lifting, settling, or uneven - appears related to the deck itself and not the structural support below - requires removal and replacement of deck

Comment: Visible evidence of a sagging or settled structure or depression in the floor line, requiring removal and replacement

Cell: J19

Comment: Deck lifting, settling, or uneven - appears related to the deck itself and not the structural support below - requires removal and replacement of deck

Cell: N19

Comment: Visible evidence of a sagging or settled structure or depression in the floor line, requiring removal and replacement

Cell: J20

Comment: Deck lifting, settling, or uneven - appears related to the deck itself and not the structural support below - requires removal and replacement of deck

Cell: N20

Comment: Visible evidence of a sagging or settled structure or depression in the floor line, requiring removal and replacement

Cell: C21

Comment: The roof structure referring to the supporting structure and the deck but excluding the roofing itself

Cell: L21

Comment: Evidence of a spongy decking from water intrusion - replacing the deck but not the trusses

Cell: N21

Comment: Visible evidence of a sagging structure or depression in the roof line, requiring removal and replacement

Cell: L22

Comment: Evidence of a flexing decking from water intrusion / rust - replacing the deck but not the trusses

Comment: Visible evidence of a sagging structure or depression in the roof line, requiring removal and replacement

Cell: L23

Comment: Evidence of a spongy / spalling deck from water intrusion - replacing the deck but not the beams Cell: N23

Comment: Visible evidence of a sagging structure or depression in the roof line, requiring removal and replacement

Cell: D25

Comment: Apply to wall surface area

Cell: J25

Comment: Surface is in tact but finish is deteriorated - paint

Cell: L25

Comment: Cracks visible - route and patch prior to painting

Cell: D26

Comment: Apply to wall surface area

Cell: J26

Comment: Surface is in tact but finish is deteriorated - paint

Cell: L26

Comment: Some blocks are damaged, needing patch and repair prior to sealing or painting

Cell: N26

Comment: There is evidence of settling, failure, or a compromised structure that requires removal and replacement

Cell: D27

Comment: Apply to wall surface area

Cell: J27

Comment: Surface is in tact but finish is deteriorated - paint

Cell: L27

Comment: A number of panels are damaged, requiring patch and repair prior to re-painting

Comment: The panels are lifting or separating or otherwise losing their integrity - remove and replace

Cell: D28

Comment: Apply to wall surface area

Cell: J28

Comment: Surface is in tact but finish is deteriorated - paint

Cell: L28

Comment: Cracks visible - route and patch prior to painting

Cell: N28

Comment: System in failure with evidence of water intrusion - remove and replace

Cell: D29

Comment: Apply to wall surface area

Comment: Minor repairs needed to mortar, prep, and re-sealing

Cell: L29

Comment: Mortar missing in a majority of areas requiring complete re-pointing and sealing

Cell: N29

Comment: Masonry visibly damaged and requiring removal and replacement

Cell: D30

Comment: Apply to glazed area

Cell: J30

Comment: The glazing is double pane but is broken or fogged and requires replacement

Comment: The glazing is single pane or the sash is damaged - either requires replacement of the sash and its glazing

Cell: N30

Comment: The structural integrity of the frame is damaged, requiring the full replacement of the window unit Cell: D31

Comment: This assumes both individual aluminum windows and storefront systems; Apply to glazed area

Cell: J31

Comment: The glazing is double pane but is broken or fogged and requires replacement

Cell: L31

Comment: The glazing is single pane or the sash is damaged - either requires replacement of the sash and its glazing

Comment: The structural integrity of the frame is damaged, requiring the full replacement of the window unit

Cell: D32

Comment: This assumes a metal windows system clad with wood or vinyl; Apply to glazed area

Cell: J32

Comment: The glazing is double pane but is broken or fogged and requires replacement

Cell: L32

Comment: The glazing is single pane or the sash is damaged - either requires replacement of the sash and its glazing

Cell: N32

Comment: The structural integrity of the frame is damaged, requiring the full replacement of the window unit

Cell: D33

Comment: Apply to glazed area Cell: J33

Comment: Minor leaks at wall seams - re-caulk and re-seal

Cell: L33

Comment: Window panels fogged and require replacement

Cell: N33

Comment: Settlement or displacement is evident

Cell: D34

Comment: Apply to door count

Cell: J34

Comment: Door hardware is damaged or non-functional and requires replacement

Cell: L34

Comment: Door panel and hardware are damaged and require replacement

Cell: N34

Comment: Door frame, door, and hardware are damaged and require replacement

Cell: D35

Comment: Apply to door count

Cell: J35

Comment: Door hardware is damaged or non-functional and requires replacement

Cell: L35

Comment: Door panel and hardware are damaged and require replacement

Cell: N35

Comment: Door frame, door, and hardware are damaged and require replacement

Cell: D36

Comment: Apply to door count

Cell: J36

Comment: Door hardware is damaged or non-functional and requires replacement

Cell: L36

Comment: Door panel and hardware are damaged and require replacement

Cell: N36

Comment: Door frame, door, and hardware are damaged and require replacement

Cell: C38

Comment: Assumes the insulation, roof covering, and associated flashings, gutters, and downspouts

Cell: D38

Comment: Apply to roof area

Cell: H38

Comment: Small number of shingles lifting and/or separation in a portion of flashing

Cell: J38

Comment: Leaks in a specific area or zone related to poor detailing and or flashing

Cell: L38

Comment: System in complete failure with multiple leaks and multiple examples of visible breaches in system - Replace roof system OVER TOP OF EXISTING

Cell: N38

Comment: System in complete failure with multiple leaks and multiple examples of visible breaches in system - REMOVE AND Replace roof system

Cell: D39

Comment: Apply to roof area

Cell: H39

Comment: Minor blistering requiring isolated patches

Cell: J39

Comment: Leaks in a specific area or zone related to poor detailing and or flashing or unchecked blisters

Cell: L39

Comment: System in complete failure with multiple leaks and multiple examples of visible breaches in system - Replace roof system OVER TOP OF EXISTING

Cell: N39

Comment: System in complete failure with multiple leaks and multiple examples of visible breaches in system - REMOVE AND Replace roof system

Cell: D40

Comment: Apply to roof area

Cell: H40

Comment: Minor blistering requiring isolated patches

Cell: J40

Comment: Leaks in a specific area or zone related to poor detailing and or flashing or seam separation

Cell: L40

Comment: System in complete failure with multiple leaks and multiple examples of visible breaches in system - Prep and re-coat roof system OVER TOP OF

EXISTING Cell: N40

Comment: System in complete failure with multiple leaks and multiple examples of visible breaches in system - REMOVE AND Replace roof system

Cell: D41

Comment: Apply to roof area

Cell: J41

Comment: Leaks are occurring and flashing at seams or transitions has separated requiring replacement of flashing and sealant

Cell: N41

Comment: Panels have lifted or separated and water intrusion is evident. Remove and replace panels and associated flashing

Cell: D42

Comment: Apply to roof area

Cell: J42

Comment: Leaks occurring at isolated areas requiring grout removal and re-grout at isolated tile locations

Cell: N42

Comment: Tiles are cracked, loose, or damaged and require removal and replacement

Cell: D43

Comment: Apply to roof opening area

Cell: J43

Comment: Minor leaking is occurring, requiring re-caulk and re-seal

Cell: N43

Comment: The panes or framing are damaged beyond repair and requires replacement

Cell: D44

Comment: Apply to roof opening area

Cell: N44

Comment: The door is non-functional or damaged beyond repair and requires replacement

Cell: D47

Comment: Apply to wall surface area

Cell: N47

Comment: There is evidence of settling, failure, or a compromised structure that requires removal and replacement

Cell: D48

Comment: Apply to wall surface area

Cell: L48

Comment: There are some blocks that are damaged and requires a strategic removal and replacement

Cell: N48

Comment: There is evidence of settling, failure, or a compromised structure that requires removal and replacement

Cell: D49
Comment: Apply to door count

Cell: J49

Comment: Door hardware is damaged or non-functional and requires replacement

Cell: L49

Comment: Door panel and hardware are damaged and require replacement

Cell: N49

Comment: Door frame, door, and hardware are damaged and require replacement

Cell: D50

Comment: Apply to door count

Cell: J50

Comment: Door hardware is damaged or non-functional and requires replacement

Cell: L50

Comment: Door panel and hardware are damaged and require replacement

Cell: N50

Comment: Door frame, door, and hardware are damaged and require replacement

Cell: D53

Comment: Apply to stair flights

Cell: L53

Comment: Rails not compliant with code and require removal and replacement

Cell: N53

Comment: Structural integrity of stair unit is compromised and requires its removal and replacement

Comment Cell: D54

Comment: Apply to stair flights

Cell: H54

Comment: Rust visible - prep and re-finish

Cell: L54

Comment: Rails not compliant with code and require removal and replacement

Comment: Structural integrity of stair unit is compromised and requires its removal and replacement

Cell: D55

Comment: Apply to stair flights

Cell: L55

Comment: An isolated structural crack or separation requiring re-enforcement in place

Cell: N55

Comment: Structural cracking and separation occurring in multiple locations - remove and replace the stair unit

Cell: D56

Comment: Apply stair tread and riser area

Cell: H56

Comment: Surface feels rough and/or taking in moisture from the surface resulting in staining - prep and re-seal

Cell: N56

Comment: Severe cracking requiring removal and replacement of tread in fills

Cell: D57

Comment: Apply stair tread and riser area

Cell: N57

Comment: finish is lifting or separating and creating trip hazards - remove and replace

Cell: D59

Comment: Apply to surface treated

Cell: H59

Comment: Surface is in tact but finish is deteriorated - paint

Cell: N59

Comment: Systemic failure of finish, possible water intrusion - requires removal and replacement

Cell: D60

Comment: Apply to surface treated

Cell: H60

Comment: Surface is in tact but finish is deteriorated - paint

Cell: J60

Comment: Surface is damaged - patching of the surface is required prior to painting

Cell: N60

Comment: Systemic failure of finish, possible water intrusion - requires removal and replacement

Cell: D61

Comment: Apply to surface treated

Cell: H61

Comment: Surface is in tact but finish is deteriorated - paint

Cell: N61

Comment: Systemic failure of finish, possible water intrusion - requires removal and replacement

Cell: D62

Comment: Apply to surface treated

Cell: H62

Comment: Grout is damaged or deteriorated

Cell: N62

Comment: Tiles are cracked or in disrepair

Cell: D63

Comment: Apply to surface treated

Cell: N63

Comment: worn or severely stained or starting to pull up / bubble

Cell: D64

Comment: Apply to surface treated

Cell: H64

Comment: sporadic number of tiles are lifting or cracked / broken and require replacement

Cell: L64

Comment: The majority of tiles are lifting, cracking / broken and require replacement - the tiles or glue are NOT asbestos

Cell: N64

Comment: The majority of tiles are lifting, cracking / broken and require replacement - the tiles or glue are asbestos

Cell: D65

Comment: Apply to surface treated

Cell: N65

Comment: Severely worn or seams separating - replace

Cell: D66

Comment: Apply to surface treated

Cell: H66

Comment: Surface feels rough and/or taking in moisture from the surface resulting in staining - prep and re-seal

Cell: N66

Comment: Significant cracking, but not differential - requires prep and crack filling prior to re-seal. If differential, refer to slab on grade of floor construction

above Cell: D67

Comment: Apply to surface treated

Cell: H67

Comment: Grout is damaged or deteriorated **Comment:** Tiles are cracked or in disrepair

Cell: D68

Comment: Apply to surface treated

Cell: N68

Comment: Systemic blistering or severely worn traffic areas - strip and replace

Cell: D69

Comment: Apply to surface treated

Cell: J69

Comment: Surface is damaged - requires sanding, repair, and re-coat / re-stripe

Cell: N69

Comment: Wood planks are deteriorated, separating, and multiple dead spots - replace floor

Cell: D70

Comment: Apply to surface treated

Cell: H70

Comment: Surface is in tact but finish is deteriorated - paint

Cell: J70

Comment: Surface is damaged - patching of the surface is required prior to painting

Cell: N70

Comment: Systemic failure of finish, possible water intrusion - requires removal and replacement

Cell: D71

Comment: Apply to surface treated

Cell: H71

Comment: Stained or damaged ceiling tiles

Cell: J/1

Comment: Diagonal bracing missing from grid

Cell: N71

Comment: Grid is sagging with tiles compromised - requires replacement of system

Cell: D72

Comment: Apply to surface treated

Cell: H72

Comment: Stained or damaged ceiling tiles

Cell: N72

Comment: Systemic failure of finish, possible water intrusion - requires removal and replacement

Cell: D73

Comment: Apply to surface treated

Cell: N73

Comment: Surface is in tact but finish is deteriorated - paint

Cell: C76

Comment: Assume standard cab-style elevator; Apply per stop

Cell: E76

Comment: Insert number of elevators * number of stories - i.e. if there are 2 elevators each going 3 stories - insert 6

Cell: H76

Comment: The elevator doors are damaged and require replacement

Cell: J76

Comment: Electrical components are not working

Cell: 176

Comment: Replacement of the hoist cables, guide rails, or other similar mechanical components is required

Cell: N76

Comment: Mechanical and electrical components have deteriorated requiring the replacement of the system

Cell: C77 Comment: Apply per flight

Cell: E77

Comment: Insert number of escalators * number of stories - i.e. if there are 2 escalators each going 3 stories - insert 6

Cell: J77

Comment: Electrical components are not working

Cell: N77

Comment: Mechanical and electrical components have deteriorated requiring the replacement of the system

Cell: C78

Comment: Assume open vertical or inclined lift; Apply per unit

Comment: Insert number of lifts

Cell: J78

Comment: Electrical components are not working

Cell: N78

Comment: Mechanical and electrical components have deteriorated requiring the replacement of the system

Cell: C80

Comment: All fixtures (toilets, urinals, sinks, showers, etc.) to be lumped together here

Cell: J80

Comment: Flush valves or faucets are non-functional and require replacement

Comment: The fixture itself is broken or is not compliant with water efficiency standards

Cell: H81

Comment: The vale stems, pressure gauges, and gate valves no longer function. Cell: J81

Comment: The insulation on the piping is in disrepair, loose, or missing.

Cell: N81

Comment: The risers are worn, damaged, or clogged beyond repair. Replacement includes the piping, insulation, and valves

Cell: H82

Comment: In some areas, there are back ups requiring the replacement of the broken floor or wall, clean outs, routing and cleaning the problem areas, and snaking floor drains

Cell: N82

Comment: The runs and risers are deteriorated, displaced, or have systemic leaks and requires full replacement

Cell: C83

Comment: This is for the presence of interior rain drains; note building percentage based on area of roof served - excludes external downspouts

Cell: 183

Comment: The rain drain or overflow is damaged and needs replacement

Cell: N83

Comment: The integrity of the piping is compromised and is leaking inside the walls

Cell: C86

Comment: This assumes gas piping

Cell: H86

Comment: The valve stems, riser gate valves, and temperature probes need to be repaired or replaced.

Comment: The risers are worn, damaged, or clogged beyond repair. Replacement includes the piping, insulation, and valves

Cell: H87

Comment: The burner is inefficient and requires refurbishment

Cell: J87

Comment: One major component needs to be replaced

Cell: L87

Comment: More than one major component needs to be replaced

Cell: N87

Comment: The system is in failure

Cell: L88

Comment: Some of the distribution fans and coils are dysfunctional.

Cell: N88

Comment: The majority of the distribution fans or coils are dysfunctional and the primary unit is in a state of disrepair

Cell: 189

Comment: A small number of minor parts need to be repaired or replaced

Cell: L89

Comment: The burner, combustion chamber, or fan are faulty and require replacement

Cell: N89

Comment: The entire furnace requires replacement

Cell: J90

Comment: A small number of minor parts need to be repaired or replaced

Cell: L90

Comment: System operating at low efficiency; shell exhibits corrosion. Retube heat exchanger

Cell: N90

Comment: System operates at low efficiency with corrosion and leaks apparent. Replace system

Cell: L91

Comment: Some of the distribution fans and coils are dysfunctional.

Cell: N91

Comment: The majority of the distribution fans or coils are dysfunctional and the primary unit is in a state of disrepair

Cell: N92

Comment: The chiller is beyond economic repair

Cell: J93

Comment: Dampers in the system are inoperative

Cell: L93

Comment: The insulation is damaged or missing

Cell: N93

Comment: The ductwork is damaged or inadequately designed and requires replacement

Cell: H94

Comment: The valve stems, riser gate valves, and temperature probes need to be repaired or replaced.

Cell: J94

Comment: The insulation on the piping is in disrepair, loose, or missing.

Cell: N94

Comment: The risers are worn, damaged, or clogged beyond repair. Replacement includes the piping, insulation, and valves

Cell: N95

Comment: Entire unit is failing to function

Cell: J96

Comment: Internal compressor is bad and requires replacement

cen: N90

Comment: Entire unit is failing to function

Cell: H97

Comment: In-room valve is failing and requires replacement

Cell: N97

Comment: Entire unit is failing to function

Cell: L98

Comment: Some of the sensors or valve actuators are dysfunctional. Replace these sensors or actuators

Cell: N98

Comment: The majority of sensors or actuators are faulty, and the system software is dysfunctional OR the system is an older / obsolete pneumatic system -

replace Cell: N99

Comment: One or more zones require re-balancing

Cell: J102

Comment: Sprinkler heads are inoperable or non-compliant and need to be replaced

Cell: N102

Comment: The piping has deteriorated or clogged or is non-compliant and needs to be replaced, including heads

Cell: J103

Comment: The Siamese twin connection, tamper flow switches, or flow control valves are inoperable and need to be replaced

Cell: N103

Comment: The fire pump is beyond repair and needs to be replaced

Cell: C104

Comment: Assume chemical extinguishing system

Cell: J104

Comment: The back-up tank has been discharged or lacks pressure and needs to be replaced

Cell: N104

Comment: The system is non-functional or not compliant with the current needs and needs to be replaced

Cell: J107

Comment: Wiring has systemic problems or does not meet code and needs to be replaced

Cell: L107

Comment: Branch panels are obsolete with replacement breakers difficult to acquire and requires replacement **Comment:** Main switchgear is obsolete or undersized and requires replacement, including service into building

Cell: L108

 $\textbf{Comment:} \ \textbf{The lighting fixtures are obsolete or non-functional and require replacement}$

Cell: N108

Comment: Replacement of fixtures is requiring the replacement of the wiring as well - includes fixtures AND wiring

Cell: J109

Comment: There are individual devices that are not functional.

Cell: L109

Comment: The master control panel is obsolete or not functional

Cell: N109

Comment: The system is obsolete or works intermittently in multiple areas and requires a system replacement

Cell: J110

Comment: There are individual devices that are not functional.

Cell: L110

Comment: The master control panel is obsolete or not functional

Cell: N110

Comment: The system is obsolete or works intermittently in multiple areas and requires a system replacement

Cell: J111

Comment: There are individual devices that are not functional.

Cell: L111

Comment: The master control panel is obsolete or not functional

Cell: N111

Comment: The system is obsolete or works intermittently in multiple areas and requires a system replacement

Cell: J112

Comment: There are individual devices that are not functional.

Cell: L112

Comment: The master control panel is obsolete or not functional

Cell: N112

Comment: The system is obsolete or works intermittently in multiple areas and requires a system replacement

Cell: J113

Comment: There are individual devices that are not functional.

Cell: L113

Comment: The master control panel is obsolete or not functional

Cell: N113

Comment: The system is obsolete or works intermittently in multiple areas and requires a system replacement

Cell: J114

Comment: There are individual devices that are not functional or in regular alarm

Cell: L114

Comment: The master control panel is obsolete or not functional

Cell: N114

Comment: The entire system is dysfunctional and constantly in trouble mode with areas not fully covered. Remove and replace system

H115 ناام

Comment: Individual room sensors are failing and require replacement

Cell: L115

Comment: The central control panel and software need upgraded

Cell: N115

Comment: The entire system is in failure and requires replacement of sensors, wiring and central panel

Cell: H120

Comment: 2-3 pieces of equipment require replacement

Cell: J120

Comment: Counters and sinks are not code compliant and require replacement with stainless steel and sink system

Cell: L120

Comment: Walk-in cooler and freezer are not functional or function intermittently and require replacement

Cell: N120

Comment: Walk-ins and kitchen design does not meet current functional requirements or has become obsolete and requires complete replacement as a full prep

kitchen Cell: H121

Comment: 2-3 pieces of equipment require replacement

Cell: L121

Comment: Mechanical and electrical service upgrades are required to meet code and amount of program equipment

Cell: N121

Comment: Both mechanical and electrical AND equipment needs replacement to meet program criteria and code

Cell: J122

Comment: Room lacking (and needing) eye wash or fume hood

Cell: L122

Comment: Sinks are in disrepair and require replacement

Comment: Work stations need upgrades to meet current program criteria - replace

Cell: J123

Comment: Storage units damaged or in disrepair

Cell: L123

Comment: Sinks are in disrepair and require replacement

Cell: N123

Comment: Work stations need upgrades to meet current program criteria - replace

Cell: E124

Comment: Insert number of seats

Cell: J124

Comment: Seats damaged and need replacement OR sound OR lighting system inadequate and needs upgraded

Cell: L124

Comment: Fly rigging in disrepair and needs upgrading

Cell: N124

Comment: 2 or more stage system dysfunctional and needs upgrade / replacement to production systems

Cell: H125

Comment: An accessory is damaged or missing

Cell: J125

Comment: Accessories need to be replaced to meet ADA

Cell: L125

Comment: The stall doors are not functional or missing and need to be replaced

Cell: N125

Comment: The restrooms stall structure is failing or needs re-configuration and needs to be replaced

Cell: D126

Comment: Note anything specific in the "Other" category at the bottom of the assessment form Cell: C129

Comment: Assume fixed casework (counters, cabinets, shelving, etc.)

Cell: H129

Comment: The counter top or exposed surface has been damaged and can be refinished

Cell: J129

Comment: The drawers and/or doors are damaged and require replacement including hardware

Cell: 1129

Comment: A combination of minor and moderate action is required, but the box is still salvageable

Cell: N129

Comment: The casework is severely damaged throughout or is obsolete for the purposes of the space and needs to be replaced

Cell: C130

Comment: Assume loose furnishings (desks, chairs, tables, etc.)

Comment: The furnishings are severely worn or are inappropriate for the age of students or function of space and require replacement

Cell: C136

Comment: Paved only or needs to be paved; Apply to surface area

Cell: E136

Comment: Indicate SF of road

Cell: H136

Comment: Minor cracking exists and can be resolved with application of a slurry coat

Cell: L136

Comment: Surface is alligatoring requiring a section to be removed down to gravel base, replaced, and region slurry coated

Comment: Surface is broken and shows evidence of heaving and/or settlement requiring removal of asphalt and over-ex of sub-grade with complete

replacement. Where there is only a gravel road and a paved one is needed, this category shall be used

Cell: C137

Comment: Paved only or needs to be paved; Apply to surface area

Cell: E137

Comment: Indicate number of stalls

Cell: H137

Comment: Minor cracking exists and can be resolved with application of a slurry coat

Cell: L137

Comment: Surface is alligatoring requiring a section to be removed down to gravel base, replaced, and region slurry coated

Cell: N137

Comment: Surface is broken and shows evidence of heaving and/or settlement requiring removal of asphalt and over-ex of sub-grade with complete

replacement. Where there is only a gravel lot and a paved one is needed, this category shall be used

Cell: C138

Comment: Concrete only or needs to be concrete; Apply to surface area

Cell: F138

Comment: Indicate square footage of walks and plazas

Cell: L138

Comment: Sections are broken with differential settlement requiring the removal of the effected panels and replacement

Cell: N138

Comment: Not only are sections of the concrete broken, but there is evidence of settlement surrounding the walk requiring removal through sub-grade and replacement. Where there is no concrete walk, but one is needed, this category shall be used

Cell: C139

Comment: Chain-link fencing; Apply to LF of fence

Cell: E139

Comment: Indicate length of fencing - assuming 6' high chain-link

Cell: L139

Comment: The fence fabric is damaged and needs to be replaced

Comment: The fencing has lost its structural integrity and is beyond repair.

Cell: C140

Comment: Irrigation systems. Other landscape or field items should be included in "Other" category at bottom of assessment form; Apply to landscape area

Cell: E140

Comment: Indicate square footage of landscaped area served (including grass areas)

Cell: N140

Comment: Irrigation system is dysfunctional and beyond repair

Cell: D142

Comment: Assumes 4" line to building. Wells should be placed in "Other" category at bottom of form; Apply to surface area

Cell: N142

Comment: A portion of the line has lost its structural integrity and requires replacement

Cell: D143

Comment: Assumes 6" line to building. Wells and holding tanks should be placed in "Other" category at bottom of form; Apply to surface area

Cell: N143

Comment: A portion of the line has lost its structural integrity and requires replacement

Cell: C144

Comment: Lines only. Septic fields, tanks, etc. should be placed in "other" category at bottom of form; Apply to surface area

Cell: N144

Comment: A portion of the line has lost its structural integrity and requires replacement

Cell: C145

Comment: Assumes underground system. For surface runoff system, apply to "Other" category at bottom of form; Apply to surface area

Cell: H145

Comment: Catch basins have lost their integrity or are out of alignment. Remove catch basin, reset, and realign

Cell: J145

Comment: Storm sewer piping is dysfunctional or damaged. Remove and replace.

Cell: L145

Comment: Detention/retention has failed, but piping and catch basins are functional. Replace detention / retention system

Cell: N145

Comment: The entire underground system has failed and requires removal and replacement of all components

Cell: C146

Comment: Apply to surface area

Cell: N146

Comment: A portion of the line has lost its structural integrity and requires replacement

Cell: C147

Comment: Apply to surface area

Cell: N147

Comment: A portion of the line has lost its structural integrity and requires replacement

Cell: C148

Comment: Natural gas lines; Apply to surface area

Cell: N148

Comment: A portion of the line has lost its structural integrity and requires replacement

Cell: D15

Comment: Assumes the private portion of the service lines typically underground after the meter or transformer; Apply to surface area

Cell: L151

Comment: The transformer no longer functions and is in need of replacement

Cell: N151

Comment: The service has failed and is beyond repair or is undersized requiring replacement of transformer and service lines

Cell: D152

Comment: Apply to generator quantity

Cell: H152

Comment: The generator needs to be tuned up

Cell: 1152

Comment: The valves or other engine parts need to be repaired or replaced and then a tune up

Cell: L152

Comment: Generator is non-functional or under-sized

Cell: N152

Comment: The system (generator, tank, services lines connected lighting system) is non-functional or under-sized

Cell: C153

Comment: Apply to surface area

Cell: J153

Comment: The fixtures are nonfunctional and require replacement

Cell: N153

Comment: The fixtures, supports, and underground wiring need to be replaced

Comment: Cell: C154

Comment: Assumes low voltage lines underground; Apply to surface area

Cell: N154

Comment: Site cabling is inadequate or service is interrupted - replace cabling

Cell: C158

Comment: For assessment professional to hand enter for specialty items and systems that do not fit into categories above