# AHERA THREE-YEAR RE-INSPECTION

Broad Street Elementary School 255 West Broad Street, Gibbstown, New Jersey 08027

**PREPARED FOR:** Greenwich Township Board of Education 415 Swedesboro Road Gibbstown, New Jersey 08027

**PREPARED BY:** Montrose Environmental, Inc. 500 Horizon Drive, Suite 540 Robbinsville, NJ 08691

**MONTROSE PROJECT NO. 257-84** 



February 2024





# TABLE OF CONTENTS

1.0 BA	ACKGROUND INFORMATION	1
1.1	INITIAL INSPECTIONS	1
	THREE-YEAR RE-INSPECTIONS	
2.0 KF	E-INSPECTION PROCEDURE	2
3.0 CC	ONCLUSIONS AND RECOMMENDATIONS	3

### **APPENDICES**

APPENDIX A:	NJDOH LETTER OF ASSURANCE
APPENDIX B:	INSPECTOR/MANAGEMENT PLANNER CERTIFICATIONS
APPENDIX C:	AHERA THREE-YEAR RE-INSPECTION FORMS
<b>APPENDIX D:</b>	FLOOR PLANS





# **1.0 BACKGROUND INFORMATION**

# 1.1 INITIAL INSPECTIONS

On October 22, 1986, President Ronald W. Reagan signed Public Law 99-519, the Asbestos Hazard Emergency Response Act (AHERA). This law required the United States Environmental Protection Agency (USEPA) to develop regulations mandating a comprehensive approach to eliminating the health hazards associated with asbestos in public and private elementary and secondary schools.

In response to this mandate, the USEPA published the Asbestos-Containing Materials in Schools Rule (40 CFR Part 763 Subpart E) on October 30, 1987. This rule required the Local Education Agency (LEA) to inspect their public and private elementary and secondary schools for friable and non-friable asbestos-containing building materials (ACBM), assess the physical condition of the ACBM, and develop an Asbestos Management Plan to address any hazards to the occupants posed by the ACBM.

The Asbestos Management Plan was also required to detail the results of all school building inspections and describing any response actions designed to control any asbestos hazards. The USEPA also mandated the designation of an individual responsible for oversight of asbestos issues.

Unless an extension was granted, the deadline for submission of the Asbestos Management Plan to the New Jersey Department of Health (NJDOH) Asbestos Control Service was October 12, 1988. LEAs were required to begin implementation of their Asbestos Management Plans by July 9, 1989.

## 1.2 THREE-YEAR RE-INSPECTIONS

One of the major provisions of the regulations is the requirement for periodic re-inspections (40 CFR 763.85). At least once every three years after the Asbestos Management Plan was implemented, the LEA must have all known friable and non-friable ACBM and presumed ACBM re-inspected. The primary purpose of the initial inspection was to locate all ACBM. The purpose of the re-inspection is to review the physical condition of the ACBM identified during the initial inspection and to detect any changes that may have occurred. This reassessment of the condition of the ACBM must be performed by an AHERA accredited inspector.

The re-inspection must include all friable and non-friable known or presumed ACBM in each school building. If, during the course of the re-inspection, the LEA becomes aware of any functional spaces and/or suspect materials missed at the time of the initial inspection, they must be inspected and assessed. The LEA has the option of either sampling any newly discovered suspect ACBM or presuming that it contains asbestos.

If the building does not contain ACBM, or if all ACBM was removed following the initial inspection, a reinspection is not necessary if the removal of all ACBM was fully documented and the records are maintained as a part of the Asbestos Management Plan.

The results of the re-inspection must be incorporated into the existing Asbestos Management Plan. Any recommendations of the management planner based on the re-inspection and any response actions selected by the LEA as a result of these recommendations also must be included.

The NJDOH does not require submission of the Re-inspection Report or a revised Asbestos Management Plan; however, a "Letter of Assurance" must be completed and returned to them once the re-inspection has been completed. A copy of the Letter of Assurance is included in **Appendix A**.





# **2.0 RE-INSPECTION PROCEDURE**

At the request of the Greenwich Township School District (District), Montrose Environmental, Inc. (Montrose) performed an AHERA re-inspection of the Broad Street Elementary School in Gibbsboro, New Jersey on February 7, 2024. Prior to the re-inspection, Montrose reviewed the existing Asbestos Management Plan, management plan addenda, site inspection data, abatement, and other pertinent records obtained from the District.

The 2024 three-year re-inspection was conducted by Mr. Taylor Chapman, an AHERA accredited Building Inspector under the supervision of Mr. Julian Fernandez-Obregon, an AHERA accredited Management Planner. The re-inspection was performed in accordance with the requirements of the EPA's Asbestos Containing Building Materials in Schools Rule (40 CFR 763.85[b]). Copies of the inspector/management planner certifications are included in **Appendix B**.

Using the available records, a current inventory of existing ACBM both confirmed and presumed was developed. Each ACBM was previously identified and recorded on the Montrose AHERA Three-Year Re-Inspection Form. Each functional space was listed on the re-inspection forms specifying the room number, homogeneous identification number and description, status and type of ACBM, friability, quantity, condition, and appropriate response action.

The areas listed on the forms were then re-inspected as follows:

- Visual re-inspection and reassessment of the condition of all friable known or presumed ACBM previously identified in the Asbestos Management Plan.
- Visual inspection of material that was previously considered non-friable ACBM to determine whether it had become friable since the last inspection.
- Identification of any homogeneous areas with material that had become friable since the re-inspection.
- Assessment of the condition of the newly friable material.

The findings of the re-inspection for all known confirmed and presumed homogeneous materials have been incorporated into Montrose AHERA Three-Year Re-Inspection Forms. The re-inspection forms are included in **Appendix C**. Floor plans depicting the locations of confirmed and presumed ACBM area included as **Appendix D**.

Note that details of damage to ABCM, if found during the re-inspection, are included on the re-inspection forms. The damaged materials should be repaired or removed as noted according to Local, State, and Federal regulations. Montrose has anticipated that damaged materials found during the re-inspection will be repaired or removed prior to the next six-month periodic surveillance.

The NJDOH adopted amendments regarding the testing and analysis of suspect Category I non-friable and other non-friable organically bound ACBM. These materials must be analyzed by Transmission Electron Microscopy (TEM) when a sample contains one-percent (1%) or less than one percent asbestos by Polarized Light Microscopy (PLM). If building materials have been previously identified as a non-ACBM by PLM, Montrose recommends performing additional testing and analysis by TEM prior to disturbance.

This re-inspection report is a supplement to the original Asbestos Management Plan and should be included as part of the plan. The findings of this re-inspection reflect site conditions observed at the time of the re-





inspection. The inspection was limited to those materials which were accessible to the re-inspection personnel. Exploratory demolition, coring, and wall and ceiling dismantlement were not performed at the time of the re-inspection. Any changes in facility use or occupancy characteristics may necessitate a reassessment. This investigation was limited to the review of existing data supplied to Montrose by the District.

This re-inspection report should not be used as a specification for an asbestos specification/removal contract. Prior to any building demolition, renovation, or repair activities, additional investigation and/or sampling may be required.

# **3.0 CONCLUSIONS AND RECOMMENDATIONS**

The AHERA Three-Year Re-Inspection completed at the Broad Street Elementary School indicates that some of the previously identified confirmed ACBM was identified as damaged or newly friable. Repairs should be made, when feasible. Montrose then recommends maintaining the existing Operation and Maintenance (O&M) Program.

Our professional services have been performed, our findings obtained, and our conclusions and recommendations prepared in accordance with customary principles and practices in the fields of environmental science and engineering. This statement is in lieu of other statements either expressed or implied. This report does not warrant against future operations or conditions, nor does it warrant against operations or conditions present of a type or at a location not investigated. The scope of services performed in the execution of this evaluation may not be appropriate to satisfy the needs of other users, and use or re-use of this document or the findings, conclusions, or recommendations is at the risk of said user.

-000-

Montrose appreciates the opportunity to assist Greenwich Township School District with this project. Should you have any questions or comments please feel free to contact us at (609) 890-7277.

Respectfully Submitted,

## MONTROSE ENVIRONMENTAL, INC.

Juli of so a

Julian Fernandez-Obregon Manager, Health & Safety Division AHERA Building Inspector/Management Planner

Faylor Chapman

Taylor Chapman Staff Health & Safety Specialist AHERA Building Inspector





# Appendix A NJDOH Letter of Assurance

### New Jersey State Department of Health Division of Occupational and Environmental Health Environmental Health Service

### LETTER OF ASSURANCE THREE-YEAR REINSPECTION OF SCHOOL BUILDINGS PURSUANT TO AHERA

### **RESPONSIBLE GOVERNING AUTHORITY**

Name of Responsible Governing Authority		Telephone Number					
GREENWICH TOWNSHIP SCHOOL DISTRIC	Т	856-224-4900					
Street Address							
415 SWEDESBORO ROAD							
Town		County					
GIBBSTOWN		GLOUCESTER					
Name of Asbestos Program Manager	Affiliation	Telephone Number					
GERARDO BATISTA	FACILITIES MANAGER	856-224-4920 X2129					
	FACILITY						
Name of Facility		Telephone Number					
BROAD STREET SCHOOL		856-224-4900					
Building Assessed		Asb. Mgt. Plan Number (if known)					
BROAD STREET SCHOOL							
Street Address							
255 WEST BROAD STREET							
Town		County					
GIBBSTOWN		GLOUCESTER					
Date Three-year Reinspection Occurred							

February 7, 2024

### INSPECTORS/ASSESSORS

	Name	Address 500 HORIZON DRIVE, SUITE 540	Telephone Number			
1	Taylor Chapman	ROBBINSVILLE, NEW JERSEY 08691	609.890.7277			
	Affiliation	Acc. No./State of Accreditation	Signature Chaman			
	MONTROSE ENVIRONMENTAL INC.	AHERA Inspector #NYSDOH 938760	Signature Faylor Chapman			
	Name	Address 500 HORIZON DRIVE, SUITE 540	Telephone Number			
2	Julian Fernandez-Obregon	ROBBINSVILLE, NEW JERSEY 08691	609.890.7277			
	Affiliation	Acc. No./State of Accreditation	Signature			
	MONTROSE ENVIRONMENTAL, INC.	AHERA Management Planner #NAETI 64888	Julin of son			
	Name	Address	Telephone Number			
3						
	Affiliation	Acc. No./State of Accreditation	Signature			

Return completed form to:

NJDOH ATT: Mr. James A. Brownlee New Jersey Department of Health Consumer and Environmental Health Services P.O. Box 369 Trenton, NJ 08625-0360





# Appendix B

Inspector/Management Planner Certifications

# **Big Apple Occupational Safety Inc**

505 Eighth Avenue, #2305, New York, NY 10018 (212) 564-7656

This Is To Certify That

Taylor Chapman

has successfully completed the New York State Department of Health approved course entitled This course meets requirements of TSCA Title II

# **Asbestos Inspector Initial**

(The official record of successful completion is the DOH 2832 Certificate of completion New York State Department of Health Certificate of Asbestos Safety Training)

Course Date: 08/07/2023 - 08/09/2023

Expiration Date: 08/09/2024

Wun Amoul

Certificate Number: 938760

Examination Date: 08/09/2023

Examination Grade: 92%

Radha Reddy Training Director

# NAETI

# CERTIFICATE OF COMPLETION

Some Bar

64888

AHERA/EPA Accredited Per 40 CFR Part 763 Asbestos Accreditation under TSCA Title II

This is to certify that

# Julian Fernandez-Obregon

Successfully completed the course entitled

1/2-Day New York State/EPA/AHERA Asbestos Management Planner Annual Refresher on October 30<sup>th</sup>, 2023

*Examination Date on October 30<sup>th</sup>, 2023* 

Expiration Date on October 30th, 2024

the Jule

Glenn Neuschwender, Greg Krueger Training Directors, NAETI

Per 10 NYCRR Part 73.2 (L) (1), DOH 2832 Certificate of Completion of Asbestos Safety Training is the only official record of training for N.Y.S. students.

ABIH 1/2 CM POINT

106 Apple SL SU 112B Finton Falls, NJ 07724 Phone (732) 531-5571

ranguage: Fughs





# Appendix C AHERA Three-Year Re-Inspection Forms



Facility Name

Broad Street Elementary School

Facility Address

255 West Broad Street

Gibbstown, New Jersey 08027

Date of Reinspection Date of Previous Reinspection

Date of Next Reinspection

Winter 2024 Fall 2020 Summer 2027

	Building Inspection												
Room #	Homogenous ID#	Homogenous ID Description	Status P/C	ACM Type T/S/M	Friable Y/N	Quantity SF/LF	Current Quantity Damaged SF/LF Condition ND/D/SD	Change Y/N	Response Action	Date: Winter 2024 Comments			
1916 1st Floor Hall	GTBS107	Grey Linoleum	Р	Т	N	800	0 SF	N	7	Maintain			
(Under Carpet)						SF	ND			O & M			
1916 1st Floor Hall	GTBS107	Mastic associated with Grey Linoleum	Р	М	Ν	800	0 SF	N	7	Maintain			
(Under Carpet)						SF	ND			O & M			
Auditorium Lobby above Drop	GG10	Pipe Insulation	Р	Т	Y	20 LF	0 SF	N	7	Maintain			
Ceiling		Light Green and Beige Spots				SF	ND			O & M			
Auditorium Lobby/ Stage	GG10	Pipe Insulation	Р	Т	Ν	150	0	N	7	Maintain			
above Plaster Celiing		White and Dark Green Spots				LF	ND			O & M			
Boiler Room	BG01	Boiler Gasket	Р	Т	N	200	12 SF	N	7	Maintain			
						LF	D			O & M			
Boy's Locker Room	GG16	Elbows/Joints associated with Fiberglass	Р	Т	Y	6	0 SF	N	7	Maintain			
and Office near Radiator		Pipe Insulation				FTG	ND			O & M			
Café Storage/Freezer	FT02	12"x12" Blue Floor Tile	Р	М	Ν	150	1 SF	Y	6	Maintain			
						SF	ND			O & M			
Café Storage /Freezer	FT02M	Mastic associated with 12"x12"	Р	М	Ν	150	1 SF	N	7	Maintain			
		Blue Floor Tile				SF	ND			O & M			
Crawlspace in Faculty Storage	GG16	Elbow/Joints associated with Fiberglass	Р	Т	Y	180	0 SF	N	7	Maintain			
Utility 2		Pipe Insulation				FTG	ND			O & M			
Custodial Office near Radiator	GG16	Elbows/Joints associated with Fiberglass	Р	Т	Y	21	0 SF	N	7	Maintain			
		Pipe Insulation				FTG	ND			O & M			
Custodial Supply	GG16	Elbow/Joints associated with Fiberglass	Р	Т	Y	8	0 SF	N	7	Maintain			
Room 1 near Room 105		Pipe Insulation				FTG	ND			O & M			
Custodial Supply Room 1	A42	Vibration Collar	Р	М	N	8	0 SF	N	7	Maintain			
						SF	ND			O & M			
Equipment Storage in Gym	FT02	9"x9" Blue Floor Tile	Р	М	N	300	0 SF	N	7	Maintain			
						SF	ND			O & M			
Equipment Storage in Gym	FT02M	Mastic associated with	Р	М	N	300	0 SF	N	7	Maintain			
		Blue Floor Tile				SF	ND			O & M			
Equipment Storage in Gym	GG16	Elbow/Joints associated with Fiberglass	Р	Т	Y	12	0 SF	N	7	Maintain			
		Pipe Insulation				FTG	ND			0 & M			
Faculty Room Storage	FT03	9"x9" Green Floor Tile	Р	М	N	40	1 SF	N	6	Maintain			
						SF	ND			O & M			
Faculty Room Storage	FT03M	Mastic associated with 9"x9"	Р	М	N	41	1 SF	N	6	Maintain			
	ļ	Green Floor Tile				SF	ND			0 & M			
Front Office in Safe	FT03	9"x9" Green Floor Tile	Р	М	N	150	0 SF	N	7	Mainttain			
						SF	ND			O & M			



Facility Name

Broad Street Elementary School

Facility Address

255 West Broad Street

Gibbstown, New Jersey 08027

Date of Reinspection Date of Previous Reinspection

Date of Next Reinspection

Winter 2024 Fall 2020 Summer 2027

	Building Inspection													
Room #	Homogenous ID#	Homogenous ID Description	Status P/C	ACM Type T/S/M	Friable Y/N	Quantity SF/LF	Current Quantity Damaged SF/LF Condition ND/D/SD	Change Y/N	Response Action	Date: Winter 2024 Comments				
Front Office in Safe	FT03	Mastic associated with 9"x9"	Р	М	N	150	0 SF	N	7	Mainttain				
		Green Floor Tile				SF	ND			O & M				
General Supply (111, Utility 4)	GG11	Compressed Paper Pipe Insulation	Р	Т	Y	5	0 SF	N	7	Mainttain				
						LF	ND			O & M				
Girls's Locker Room	GG16	Elbows/Joints associated with Fiberglass	Р	Т	Y	6	0 SF	N	7	Mainttain				
and Office near Radiator		Pipe Insulation				LF	ND			O & M				
Ground Floor Room	GG10	Pipe Insulation	Р	Т	Y	20	0 SF	N	7	Mainttain				
1916 above Drop Ceiling						LF	ND			O & M				
Gym near 30' Ceiling	GTBS104	Vibration Collar	Р	М	N	10	0 SF	N	7	Mainttain				
						SF	ND			O & M				
Gym near Ceiling	GG16	Elbows/Joints associated with Fiberglass	Р	Т	Y	12	0 SF	N	7	Mainttain				
		Pipe Insulation				FTG	ND			O & M				
Hall A above Tin Drop Celiing	GG10	Pipe Insulation	Р	Т	Y	140	0 SF	N	7	Mainttain				
						LF	ND			O & M				
Hall E above Drop Ceiling	GG16	Elbows/Joints associated with Fiberglass	Р	Т	Y	6	0 SF	N	7	Mainttain				
		Pipe Insulation				FTG	ND			O & M				
Hall Ground Floor	GG10	Pipe Insulation	Р	Т	Y	22	0 SF	N	7	Mainttain				
						LF	ND			O & M				
Kitchen Crawl Space	GG16	Elbow/Joints associated with Fiberglass	Р	Т	Y	50	0 SF	N	7	Mainttain				
w/ Access Door across 11,12		Pipe Insulation				FTG	ND			O & M				
Room back	GG16	Elbow/Joints associated with Fiberglass	Р	Т	Y	4	0 SF	N	7	Mainttain				
Storage		Pipe Insulation				FTG	ND			O & M				
Lamination Room	FT04	9"x9" Red Floor Tile	Р	М	N	50	0 SF	N	7	Mainttain				
						SF	ND			O & M				
Lamination Room	FT04M	Mastic associated with 9"x9"	Р	М	N	50	0 SF	N	7	Mainttain				
		Red Floor Tile				SF	ND			O & M				
Carpet and linoleum)	GG14	9"x9" Floor Tile and Mastic	Р	Т	N	250	0 SF	N	7	Maintain				
						SF	ND			O & M				
Nurse's Office	GG9	12"X12" White with Brown Floor Tile	Р	М	N	198	0 SF	Y	7	Maintain				
8, 9		and Mastic				SF	ND			O & M				
Gymnasium)	GTBS105	Transite Panels	Р	М	N	4,600	0 SF	N	7	Maintain				
			4		ļ	Ea	ND			O & M				
Classrooms in	GG10	Pipe Insulation	Р	Т	Y	140	0 SF	N	7	Maintain				
1930 Wing	ļ		+			LF	ND			O & M				
Room 101 (under new flooring)	GG14	9"x9" Floor Tile and Mastic	Р	М	N	672	0 SF	N	7	Maintain				
			+			SF	ND			O & M				
Room 102	GG16	Elbow/Joints associated with Fiberglass	Р	Т	Y	6	0 SF	N	7	Maintain				
1P		Pipe Insulation				FTG	ND			O & M				
Room 104	GG16	Elbows/Joints associated with Fiberglass	Р	Т	Y	9	0 SF	N	7	Maintain				
		Pipe Insulation			<u> </u>	FTG	ND			O & M				



Facility Name

Broad Street Elementary School

Facility Address

255 West Broad Street Gibbstown, New Jersey 08027 **Date of Reinspection Date of Previous Reinspection** 

Date of Next Reinspection

Winter 2024 Fall 2020 Summer 2027

	Management Planning									
Room #	Homogenous ID#	Homogenous ID Description	Status P/C	ACM Type T/S/M	Friable Y/N	Quantity SF/LF	Current Quantity Damaged SF/LF Condition ND/D/SD	Change Y/N	Response Action	Date: Winter 2024 Comments
Room 105 Library	GG16	Elbow/Joints associated with Fiberglass	Р	Т	Y	50	0 SF	N	7	Maintain
		Pipe Insulation				FTG	ND			O & M
Room 105 Library	GG16	Elbow/Joints associated with Fiberglass	Р	Т	Y	20	0 SF	N	7	Maintain
		Pipe Insulation				FTG	ND			O & M
Room 105A Library	GG16	Elbow/Joints associated with Fiberglass	Р	Т	Y	8	0 SF	N	7	Maintain
		Pipe Insulation				FTG	ND			O & M
Room 106	GG10	Pipe Insulation	Р	Т	Y	20	0 SF	N	7	Maintain
						LF	ND			O & M
Room 106	GG11	Compressed Paper Pipe Insulation	Р	Т	Y	30	0 SF	N	7	Maintain
		With Grey Spots				LF	ND			O & M
Room 107	FT01	12"X12 White/Tan Floor Tile	Р	М	N	800	0 SF	N	7	Maintain
						SF	ND			O & M
Room 107	FT01M	Mastic assciated with 12"x12"	Р	М	N	800	0 SF	N	7	Maintain
		White /Tan Floor Tile				SF	ND			O & M
Room 108	GG11	Compressed Paper Pipe Insulation	Р	Т	Y	30	0 SF	N	7	Maintain
						LF	ND			O & M
Room 111- Custodial	GG10	Pipe Insulation	Р	Т	Y	12	0 SF	N	7	Maintain
Supply 8' from Floor						LF	ND			O & M
Room 212	L01	Tan Linoleum	Р	М	N	720	1 SF	Y	5	Repair, then Maintain
						SF	D			O & M
Room 213	FT01	12"x12" Tan and White Floor Tile and Mastic	Р	М	N	720	0 SF	Y	5	Repair, then Maintain
						SF	ND			O & M
Room 215	L01	Tan Linoleum	Р	М	N	720	0 SF	Y	6	Maintain
	-					SF	ND		-	O & M
Room 216	L02	Tan Linoleum	Р	М	N	721	1 SF	N	4	Repair, then Maintain
						SF	D			O & M
Room 223 &	GG14GN	9"X9" Green Floor Tile and Mastic	Р	М	N	160	0 SF	N	7	Repair, then Maintain
Closet (under carpet)						SF	ND			O & M
Storage Room Office	GG10	Pipe Insulation	Р	т	Y	15	1 LF	Y	5	Repair, then Maintain
	0010		1			LF	D	·	Ŭ	O & M
Teacher's Kitchen next to Lounge	GG9	12"X12" White with Brown Floor Tile	Р	М	N	30	0 SF	N	7	Maintain
	000	and Mastic				SF	ND		'	O & M
The Well above Drop Celing	GG16	Elbow/Joints associated with Fiberglass	Р	т	Y	6	0 SF	N	7	Maintain
	0010	Pipe Insulation	'	'		FTG	ND		'	O & M
Throughout Building	A49	Plaster	Р	S	Y	20000+	0 SF	N	7	Maintain
	A49	FIASLEI		3		20000+ SF	ND	IN	'	O & M
Room 3, 4, 5, 6, 7, 10, Behind	A49	Plaster (damaged)	Р	S	Y	200	200 SF	N	4	Repair, then Maintain
	A49	Flaster (uarriageu)		3				IN	4	
Stage, Stairwell 6						SF	D			O & M



Facility Name		Broad Street Elementary School			Date of Reinspection Date of Previous Reinspection			Winter 2024		
Facility Address		255 West Broad Street							-	
		Gibbstown, New Jersey 08027						Date of Next	Reinspection	Summer 2027
		Building	Inspect	ion						Management Planning
Room #	Homogenous ID#	Homogenous ID Description	Status P/C	ACM Type T/S/M	Friable Y/N	Quantity SF/LF	Current Quantity Damaged SF/LF Condition ND/D/SD	Change Y/N	Response Action	Date: Winter 2024 Comments
Inspector Name/#	-	Taylor Chapman (#NYSDOH 938760	)				Management Plar	ner Name/#	Julian Fernan	dez-Obregon (NAETI #64888)
Inspector Signature KEY TO CODES:		Faylor Chap	man				Management Plar	nner Signature	Jue	in also
LOCATION			ACM					RESPONSE		
F = Floor				urfacing				-	• •	Isolate, Remove Immediately
W = Wall					•	nsulation		2 = Damageo		r Significant Damage - Remove, Enclose,
C = Ceiling			M = N	liscellane	eous Mat	erial			•	or Repair when Feasible
AC = Above Ceiling							3 = Damaged & Potential for Damage - Remove, Enclose,			
TSI = Thermal Systems Ins			DITION			•			or Repair when Feasible	
O = Other				No Dama	age			-		capsulate, Enclose, or Repair When Feasible
				amage						Damage - Reduce Potential for Damage
STATUS			SD =	Significa	nt Dama	ge			for Damage - N	
P = Presumed ACM								7 = Intact, lov	v Potential for I	Damage - Maintain O&M

- QUANTITY
- SF = Square Feet LF = Linear Feet

C = Confirmed





# Appendix D Floor Plans



