Lead Testing Final Report

For test points at or above 5 ppb lead content, per §160.077, secure water and discontinue use until remediated unless testing proves that flushing will provide water below 5ppb.

144 Test points were identified:

The 24 points listed in the table below indicated greater than 5parts per billion during the initial draw sampling phase.

21 outlets have permanent "Hand Wash Only" signage placed near the faucet.

3 were successfully remediated.

If you desire further health information, you can contact your county health department:

Benton County Health Department

Warsaw, MO · (660) 438-2876

Lab results are available on the school website.

Initial	Flush	1st Re- medial	1st Re- medial Flush	Location	Action / Result
19.60	ND	1.14	ND	BASKETBALL CONCESSION FOOD PREP SINK SCULLERY SPRAYER	successfully remediated
8.42	ND	ND	ND	HS RM1 HOME ECON FOOD PREP SINK ON RIGHT	successfully remediated
6.00	1.04	*	*	HS RM6 SCIENCE FRONT ISLAND HAND SINK ON LEFT	signage installed
25.40	ND	*	*	HS RM6 SCIENCE MIDDLE ISLAND HAND SINK ON RIGHT	signage installed
9.47	ND	*	*	HS RM7 SCIENCE HAND SINK	signage installed
21.50	ND	1.55	ND	KITCHEN SCULLERY SPRAYER	successfully remediated
44.00	3.68	*	*	ELEM RM26 MUSIC HAND SINK	signage installed
30.80	4.73	*	*	ELEM LIBRARY HAND SINK	signage installed

22.40	1.92	*	*	ELEM RM28 HAND SINK	signage installed
46.00	1.47	*	*	ELEM RM29 HAND SINK	signage installed
17.80	1.66	*	*	ELEM RM30 HAND SINK	signage installed
26.50	2.34	*	*	ELEM RM31 HAND SINK	signage installed
16.20	2.52	*	*	ELEM RM32 HAND SINK	signage installed
21.00	2.02	*	*	ELEM RM33 HAND SINK	signage installed
14.20	ND	*	*	ELEM RM34 HAND SINK	signage installed
8.50	ND	*	*	ELEM RM35 HAND SINK	signage installed
21.70	ND	*	*	ELEM RM36 HAND SINK	signage installed
19.50	ND	*	*	ELEM RM36 RR SINK	signage installed
9.27	ND	*	*	ELEM RM37 HAND SINK	signage installed
5.26	ND	*	*	ELEM RM37 RR SINK	signage installed
8.08	ND	*	*	ELEM RM39 HAND SINK	signage installed
19.10	1.40	*	*	ELEM RM40 HAND SINK	signage installed
12.50	ND	*	*	ELEM RM41 HAND SINK	signage installed
13.80	ND	*	*	ELEM RM43 HAND SINK	signage installed

The next full round of testing will be in the 28/29 school year.