

**State Report**

School NCES ID	n/a
Name of School	Lincoln R-II
Address	101 W Lamine St. #39
	Lincoln, MO 65338
Type of Facility	Public
Program Remediation trigger	5ppb
School District	Lincoln R-II
Sampling Begin Date	5/29/2024
Sampling End Date	1/10/2025

Number of Sample Points tested	<b>130</b>
Number of Samples with lead Detected	<b>72</b>
Percentage of Samples with Lead Detected	<b>55.4%</b>
Number of Samples with lead Detected Above the Program Remediation Trigger	<b>24</b>
Percentage of Samples with Lead Above the Remediation Level	<b>18.46%</b>
Lab Reporting Limit	<b>1.0</b>
Number of potential drinking outlets inventoried.	<b>144</b>
Total number of samples collected and tested	<b>160</b>

Drinking water outlet type (**≥5ppb**) in the following outlet categories at each facility/campus location based on initial samples

OUTLET TYPE	ELEMENTARY			HIGH SCHOOL		
Fountains/bottle fillers	0			0		
kitchen outlets	0			1		
bathroom outlets	0			0		
Classroom	18			5		
ice makers	0			0		
hot drink machines	0			0		
other outlets-Hydrants, showers etc.	0			0		
<b>Total FAILED OUTLETS</b>	<b>18</b>			<b>6</b>		
<b>TOTAL # of outlets at each facility</b>	<b>50</b>			<b>94</b>		
TOTAL # OF SAMPLES COLLECTED/FACILITY	INITIAL	FLUSH	REMEDIAL	INITIAL	FLUSH	REMEDIAL
	49	18	0	81	6	6

Summary of remediation methods	
Number of outlets replaced	<b>2</b>
Number of outlets repaired	<b>0</b>
Number of filters installed	<b>1</b>
Number of outlets taken out of service	<b>0</b>
Number of other (signage posted)	<b>21</b>
Were interior pipes replaced	<b>NO</b>
Number of outlets tested post remediation	<b>3</b>
Additional Information	
3 water Main Test Points are included in the total number of test points.	