

Asbestos Testing Results – Clatskanie Elementary School/Bus Garage		
Location:	Material Tested:	Test Result:
Classrooms	Ceiling tiles & mastic	Good
Staff	1' blue/red tile	Good
Bus Barn	CAB	Good
Stage Prop	9" tan tile	Good
Throughout	Mastic	Good
Boiler Room	Transite board	Good
Custodian	9" tan tile	Fair
Gym	9" tan tile	Good
Old Cafeteria	9" tan tile	Good
Kitchen	1' white tile	Good
Cafeteria	Moulding mastic	Good
Cafeteria	Ceiling tile	Good
Classes	1' tan red tile	Good
Music Closet	Tan linoleum	Good
Stage	9" ceiling tiles	Good
Gym	Ceiling tile	Good
Hall	1' green tile	Good
Shop Office	Tan linoleum	Good